

**ASSIGNMENT**

Surveyor: Kenneth

DOI: 03/02/15

Assg Date: 03/02/15  
04/02/15

Pre-assign / CCU / FTE



Insured Vehicle No.: GV 6263 U  
Name of Insured: Sim Wan Sang Trucking co  
Insured Tel No.: \_\_\_\_\_ HP: \_\_\_\_\_  
Excess Sec II :SS \_\_\_\_\_ D.O.A: 31/01/15

Claim No.: 0997248 > E SG  
Policy No.: 0100247657  
Make / Model: Toyota  
Place of Accident: Paya Lebar Rd

Is driver the owner? ( YES / NO ) Nature of Accident: \_\_\_\_\_  
OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age: Eoh Boon Phinaw


Driver Tel No.: 8121 0282 (V/L: YES / NO Insured Liability: \_\_\_\_\_ % Final? Yes / No




SHC 5450P  
INSRS: \_\_\_\_\_  
WSP: Trans Cab  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/ Time	FOR CSO ONLY:	STAGE	DATE / PIC
5/2/15	Is driver the owner? ( YES / NO )	Finalisation:	
<u>Positive</u>	If NO, Driver Name / Age : _____	Email AIG for OI GIA:	
	Driver's Own Vehicle Number: _____ Insurance Company: _____	Apt letter to OI:	
	<u>SHC 5450P - CC3 / AXA 14002074 / KSA3C3 ; DPA 18/1/14</u>	Call OI:	<u>09/02/15</u>
	<u>GV 6263 U - X</u>	After call ltr to OI:	<u>Puber</u>
5/2/15	Unable to check DL. ✓	Type Report:	<u>PCB</u> <u>10/2/15</u>
		Prepare Invoice:	
		Others:	
		Documentation Check List:	Handler Typist
09/02/15	@ 3.13pm Spoken to OAD. OAD confirmed accident detail: OAD changing lane from lane 3 to lane 2 after OAD fully entered the lane, suddenly TP's vehicle also changed lane from lane 1 to lane 2 & hit onto OAD's vehicle rear right. Informal TP claim. DISPUTED ON L2AB2122y & aware NCD. Send letter to OAD's company attn: The Management	<input checked="" type="checkbox"/> OI Apt Ltr. <input type="checkbox"/> Authorisation To Act. <input type="checkbox"/> Release Voucher. <input type="checkbox"/> Final Repair Bill. <input type="checkbox"/> Car Rental Invoice. <input type="checkbox"/> LTA / GIA : <input type="checkbox"/> Medical Bill. <input type="checkbox"/> Approval Email. <input type="checkbox"/> Payment Breakdown Form. <input type="checkbox"/> Others:	
09/02/15	Email sent to TP workshop liability unclear got video footage.		
09/02/15	@ 3.20pm Spoken to OAD's witness, he confirmed accident detail: OAD changing lane from lane 3 to lane 2 after 3/4 entered the lane. Suddenly TP's vehicle also changing lane from lane 1 to lane 2 & hit onto OAD's vehicle rear right. Told witness if we require bus written statement we will call him again. (After 5.30pm then call him) conflicting version		

<b>FINAL SETTLEMENT</b>	Date: _____	Confirm with _____	<b>NO SETTLEMENT.</b>
Repair Cost:	SS _____	Final Liability _____	50 % (Agreed / Assessed)
Loss of Rental:	SS _____	( _____ days)	BOLA S/N No.: _____
Loss of Use:	SS _____	(\$ _____ x _____ days)	If NO or B 28, Ass. Lia: _____
Disbursement:	SS _____		Format Type: <b>COPY SENT</b>
Total:	SS _____	Global Sum: SS _____	WP- \$250 x 2 320 + \$20







# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG15002074/Kkdm3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 04-02-2015	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	GV 6263U	Veh. Inspected	SHC 5950P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	04/02/2015
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer		Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	31/01/2015	Inspection Date	03/02/2015
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHC 5950P -**

**ROEL**

*Not Authored*  
*1-B-1*  
*83634.98*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :

**SHC 5950P - ROEL**  
 VF1ABL15AUC280986  
 RENAULT  
 LATITUDE  
 31.01.15  
 AG

		<b>PART</b>		<b>LIST</b>
1	1	BUMPER COVER FRT	\$	<i>CR</i> 807.32 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>SR</i> 253.00 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 585.95 X
4	1	BUMPER RETAINER FRT LH	\$	<i>nd</i> 97.06 ✓
5	1	BUMPER SUPPORT FRT LH	\$	<i>SR</i> 15.31 X
6	1	BONNET	\$	<i>R</i> 1,244.63 X
7	1	AIR CLEANER LOWER	\$	<i>SR</i> 226.05 X
8	1	STEERING PUMP ELECTRIC	\$	<i>SR</i> 1,285.90 X
9	1	HEADLAMP LH	\$	<i>SR</i> 759.25 X
10	1	FENDER PANEL FRT LH	\$	<i>R</i> 502.46 ✓
11	1	FENDER WHEELARCH FRT LH	\$	<i>SR</i> 89.44 X
12	1	LOWER ARM LH	\$	<i>SR</i> 439.59 X
13	1	KUNCKLE ARM LH	\$	<i>SR</i> 542.94 X
14	1	ABSORBER FRT LH	\$	<i>SR</i> 231.12 X
15	1	DOOR MIRROR LH	\$	<i>CR</i> 950.90 ✓
16	1	DOOR PANEL FRT LH	\$	<i>R</i> 1,823.50 X
17	1	DOOR SEAL FRT LH	\$	<i>CR</i> 46.68 ✓
17	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 633.01 X

<b>TOTAL</b>	<b>\$</b>	<b>10,534.11</b>
<b>10%</b>	<b>\$</b>	<b>1,053.41</b>
	<b>\$</b>	<b>9,480.70</b>

**Special Nett**

1SET	FRONT BUMPER CLIP	\$	<i>SR</i> 66.00 ✓
1SET	BUMPER RETAINER CLIP FRT LH	\$	<i>SR</i> 15.20 X
1SET	WHEELARCH CLIP (Necessary)LH	\$	<i>SR</i> 66.00 X
1	CAP HUB LH FRT	\$	<i>SR</i> 35.00 X
1	RIM LH FRT	\$	<i>SR</i> 385.00 X
1	TYRE LH FRT	\$	<i>SR</i> 330.00 X
1	DOOR STICKER "Trans-cab"	\$	<i>SR</i> 80.00 <i>60.00</i> ✓

**TRANS-CAB AUTO SERVICES PTE LTD**  
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346  
 TEL NO.6287 6666 FAX NO.6366 8862  
 CO/GST REG NO.201019626G  
**SHC 5950P -**

ROEL

1 DOOR STICKER "Classic" \$ *Net* 30.00 ✓

**TOTAL \$ 1,007.20**

**TOTAL PARTS \$ 10,487.90**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same \$ 2,800.00 *500*

To Check Electrical Lighting Concerned. \$ 170.00 *15*

Putty and spray painting of the affected portion. \$ 3,000.00 *660*

To transfer of tire, rim and on wheel balancing. \$ *Net* 170.00 *X*

To check steering geometry and computer wheel alignment \$ 220.00 *60*

To transfer of door fittings, attachment and perform water seepage test. \$ *Net* 170.00 *X*

To rust-proofing of the affected areas. \$ 170.00 *30*

Towing Fees \$ 120.00 *50*

**TOTAL \$ 6,700.00** *6820*

**Over All Total \$ 17,187.90**

*17307.90*

**(PARTS BY PARTS) Repair Days**

**10 DAYS**

*3 days*

Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE

**IMPORTANT NOTE** : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPA 215012783      Vehicle Registration No : GV 6263 U  
Name(as shown in NRIC): SH LIAN SENG TRADING CO  
(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate  
NRIC/Passport No : N/A  
Address : \_\_\_\_\_  
Contact (Tel) : 07789845      (H/P) : 81210858  
(Email) : \_\_\_\_\_  
Date of Accident : 31/01/2015      Time of Accident : 1320  
Place of Accident : Payn Lebar Road  
Insurance Company : AIQ

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

TO CHANGE FROM AXA TO AIQ

  
\_\_\_\_\_  
Signature of Vehicle Owner / Driver

Date: 03/02/2015

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030

## Pauline Yap

---

**From:** Pauline Yap  
**Sent:** Monday, 9 February, 2015 4:13 PM  
**To:** 'claims@transcabservices.com.sg'  
**Cc:** Jasmine Tan; 'zhewei.kek@transcabservices.com.sg'; 'tzeyong.lui'; Rosey Naing  
**Subject:** Your Ref : SHC5950P \* Our Ref : CC3/AIG15002074/Kkdm3 -ACCIDENT INVOLVING VEHICLES GV6263U (OI ) AND SHC5950P (TP ) DOA ON 31/01/2015  
**Attachments:** OI's statement & sketch plan.pdf

### WITHOUT PREJUDICE

Your Ref : SHC5950P

Our Ref : CC3/AIG15002074/Kkdm3

Dear Sir/Mdm,

### ACCIDENT INVOLVING VEHICLES GV6263U (OI ) AND SHC5950P (TP ) DOA ON 31/01/2015

We refer to the above matter.

We are of the opinion that this is a case of **conflicting versions**. There is no conclusive evidence yet to substantiate either party's version. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, kindly forward to us with any evidence (if any) your client have to support your claim.

*Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.*

*In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.*

Thank you.

Best Regards,

**Pauline Yap Poh Ling** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [paulineyap@lkkauto.com](mailto:paulineyap@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



2015

Happy New Year!

## Pauline Yap

---

**From:** Zhe Wei [zhewei.kek@transcabservices.com.sg]  
**Sent:** Friday, 13 February, 2015 2:18 PM  
**To:** 'Roel'  
**Cc:** 'Jasmine Tan'; 'tzeyong.lui'; claims@transcabservices.com.sg; Rosey Naing; Pauline Yap  
**Subject:** RE: Your Ref : SHC5950P \* Our Ref : CC3/AIG15002074/Kkdm3 -ACCIDENT INVOLVING VEHICLES GV6263U (OI ) AND SHC5950P (TP ) DOA ON 31/01/2015

Hi Roel,

Kindly assist in forwarding a copy of witness's statement to Ms Pauline.

Thank you.

*Kindly quote our reference in your future replies to us.*

*Best Regards,  
Kek Zhewei*

---

**From:** Pauline Yap [mailto:paulineyap@lkkauto.com]  
**Sent:** Monday, February 09, 2015 4:13 PM  
**To:** claims@transcabservices.com.sg  
**Cc:** Jasmine Tan; zhewei.kek@transcabservices.com.sg; tzeyong.lui; Rosey Naing  
**Subject:** Your Ref : SHC5950P \* Our Ref : CC3/AIG15002074/Kkdm3 -ACCIDENT INVOLVING VEHICLES GV6263U (OI ) AND SHC5950P (TP ) DOA ON 31/01/2015

### WITHOUT PREJUDICE

Your Ref : SHC5950P

Our Ref : CC3/AIG15002074/Kkdm3

Dear Sir/Mdm,

### ACCIDENT INVOLVING VEHICLES GV6263U (OI ) AND SHC5950P (TP ) DOA ON 31/01/2015

We refer to the above matter.

We are of the opinion that this is a case of **conflicting versions**. There is no conclusive evidence yet to substantiate either party's version. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, kindly forward to us with any evidence (if any) your client have to support your claim.

*Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.*

*In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.*

Thank you.

Best Regards,

**Pauline Yap Poh Ling** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [paulineyap@lkkauto.com](mailto:paulineyap@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**2015**

Happy New Year!

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Feb 2015 14:46 <a href="#">Edit Reg</a>		03 Feb 2015 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$3,634.98</b> <a href="#">Edit Estimates</a>	<b>S\$3,634.98</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
<b>Insured:</b>	SIN LIAN SENG TRADING CO, NRIC: -	
<b>Main Claimant:</b>	TRANS-CAB SERVICES PTE LTD, NRIC: 200303878K	
<b>Vehicle Reg. No.:</b>	SHC5950P	<b>Date of Loss:</b> 31/01/2015 13:00 - :59
<b>Claim Type:</b>	TP / 099735482SSG	<b>Policy/Cover Note No.:</b> 0100247657 Coverage: 27/08/2014 - 26/08/2015
<b>Vehicle Reg. No. (Insured):</b>	GV6263U	<b>Policy No. (Claimant):</b> D-12047359MFSH/
		<b>Excess:</b> S\$
<b>Repairer:</b>	Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1, 729346 Sungei Kadut - Tel: 62876666	
<b>Handling Insurer:</b>	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd. Mokhtar, Mawar Ayuni]	
<b>Claimant's Insurer:</b>	First Capital Insurance Ltd (HQ) - Tel: 62222311	
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/02/2015]	
<b>Driver/Custodian (Insured):</b>	GOH BOON PHIAW (), NRIC: S0642878I	

[View All](#) [Compose Case Mail](#)

---

**ASSOCIATED MAIL RECEIVED**

- AIG\_SG (23/07/2015): tp

---

**ALL ASSOCIATED TASKS**

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

### Claim Documents

**\*SHC5950P (0997354825SG)**  
**[GV6263U]**  
**TP**  
**TRANS-CAB SERVICES PTE LTD**  
**Jan 31 2015 1:00PM**  
**[SIN LIAN SENG TRADING CO]**  
**Trans-cab Auto Services Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		<b>View</b> Use Viewer	
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
2	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
3	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
4	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
5	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
6	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
7	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
8	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
9	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
10	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
11	04/02/15 19:45	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
12	04/02/15 19:45	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
13	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
14	04/02/15 19:45	General View		Load JPG	<input checked="" type="checkbox"/>		
<b>Documentation</b>						1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	04/02/15 19:44	TP ESTIMATE		Load PDF			
2	04/02/15 19:44	TP GIA & POLICE REPORT		Load PDF			
3	14/12/15 17:42	APPROVAL TO WP		Load PDF			
4	16/12/15 15:27	LETTER TO OI		Load PDF			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	04/02/15 16:56	OI GIA REPORT		Load PDF			

### Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933  
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG15002074/KJA3S2  
**Date:** 16/12/2015

#### REFERENCE

**Handling Insurer:** AIG Asia Pacific Insurance Pte. Ltd. **Policy No:** 0100247657  
**Claimant Vehicle No :** SHC5950P **Insured Vehicle No :** GV6263U  
**Date of Loss:** 31/01/2015 **Nature of Claim:** TP **Claim No:** 0997354825SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

**Reg No:** SHC5950P  
**Make & Model:** RENAULT LATITUDE, 2.0 D dCi (A) **Engine No:** M9R8839C002160  
**Reg. Date:** 18/12/2014 (Man. Year: 2014) **Chassis No:** VF1ABL15AUC280986  
**Colour:** Metallic White/Red **Odometer:** 16254 km  
**Engine Capacity:** 1995 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** Market Value/New Car Price

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

**General Condition:** Good **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

#### CONDITION OF TYRES

**Front Tyre Size:** 215/60R16 **Rear Tyre Size:** 215/60R16  
**Front Left Side:** Goodyear 9 mm **Rear Left Side:** Goodyear 8 mm  
**Front Right Side:** Goodyear 9 mm **Rear Right Side:** Goodyear 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,487.90	2,319.98	8,167.92	77.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,820.00	1,315.00	5,505.00	80.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,307.90</b>	<b>3,634.98</b>	<b>13,672.92</b>	<b>79.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,211.55</b>	<b>254.45</b>	<b>957.10</b>	<b>79.00</b>
<b>Nett Amount (S\$)</b>	<b>18,519.45</b>	<b>3,889.43</b>	<b>14,630.02</b>	<b>79.00</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

#### INSPECTION

**Date of Assignment:** 03/02/2015  
**Date Inspected:** 03/02/2015 **Inspected At:** Trans-cab Auto Services Pte Ltd (HQ)  
No. 42 Sungei Kadut St 1  
Singapore 729346  
**Estimated Period of Repair:** 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** Joy Irene Bascao

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Cracked	807.32 FL	*807.32 FL
2	1		*BUMPER ABSORBER FRT	Serviceable	253.00 FL	*- FL
3	1		*BUMPER BEAM FRT	Repair	585.95 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Dented	97.06 FL	*97.06 FL
5	1		*BUMPER SUPPORT FRT LH	Serviceable	15.31 FL	*- FL
6	1		*BONNET	Repair	1,244.63 FL	*- FL
7	1		*AIR CLEANER LOWER	Serviceable	226.05 FL	*- FL
8	1		*STEERING PUMP ELECTRIC	Serviceable	1,285.90 FL	*- FL
9	1		*HEADLAMP LH	Serviceable	759.25 FL	*- FL
10	1		*FENDER PANEL FRT LH	Bent	502.46 FL	*502.46 FL
11	1		*FENDER WHEELARCH FRT LH	Serviceable	89.44 FL	*- FL
12	1		*LOWER ARM LH	Serviceable	439.59 FL	*- FL
13	1		*KNUCKLE ARM LH	Serviceable	542.94 FL	*- FL
14	1		*ABSORBER FRT LH	Serviceable	231.12 FL	*- FL
15	1		*DOOR MIRROR LH	Cracked	950.90 FL	*950.90 FL
16	1		*DOOR PANEL FRT LH	Repair	1,823.50 FL	*- FL
17	1		*DOOR SEAL FRT LH	Cut	46.68 FL	*46.68 FL
18	1		*ROCKER PANEL OUTER LH	Repair	633.01 FL	*- FL
19	1		*SET FRONT BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
20	1		*SET BUMPER RETAINER CLIP FRT LH	Not Necessary	15.20 FS	*- FS
21	1		*SET WHEELARCH CLIP LH	Not Necessary	66.00 FS	*- FS
22	1		*CAP HUB LH FRT	Serviceable	35.00 FS	*- FS
23	1		*RIM LH FRT	Serviceable	385.00 FS	*- FS
24	1		*TYRE LH FRT	Serviceable	330.00 FS	*- FS
25	1		*DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
26	1		*DOOR STICKER CLASSIC	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>11,541.31</b>	<b>2,560.42</b>
- List Item Discount on L Items 10.00/10.00% (S\$)	1,053.41	240.44
<b>Total Parts (S\$)</b>	<b>10,487.90</b>	<b>2,319.98</b>

Report was unsubmitted during this print-out.

**Recommended Miscellaneous Items**

There are no new miscellaneous items selected.

**Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	2,800.00	500.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	15.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	660.00
4	TO TRASNFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	60.00
6	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
7	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	30.00
8	TOWING FEES.	New	120.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>6,820.00</b>	<b>1,315.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >