

SKC1494E
 Volkswagen Passat CC
 WNWZZZ3CZCE517738

TP Budget Direct
 Yonne.

Rear RH Door	Dented	1685	✓
Rear RH Door Lock	Damaged	298	✓
Rear RH Door Weatherstripe	new	325	✓
Rear RH Door Outer Handle	wt	458	✓
Rear RH Door Lower Chrome Moulding	wt	231	✓
Rear RH Door Zmes Trim Board	} NP } per	1477	+
Rear RH Door Zmes Trim Board Clips		50	+
Rear RH Door Regulator Gears		395	+
Rear RH Fender	Repair	1348	+
Rear RH Wheel Rim	wt	1200	700(SN)
Rear RH Tyre	HP M	480(SN)	+
Rear RH Shock Absorber	} NP } per	452	+
Rear RH Lower Arm		470	+
Rear RH Knuckle Arm		1007	+
Rear RH Wheel Hub c/w Bearings	Damaged	385	✓
Rear Bumper	Repair	1109	+
Rear Bumper Clips	} NP } per	50	+
Rear Bumper Side Holder RH		58	+
Rear Bumper Chrome Moulding		351	+
Rear Windscreen Moulding	} NP } per	135	+
Rear Windscreen Sealant		60(SN)	+

3382

SN. 700

3212.90

SKC1494E.

Panel Beating	800	500
Spray Painting	800	600
Wiring	50	30
To remove upholstery	150	60
To remove reverse sensor	100	X
To remove rear windscreen.	180	X
To transfer door fittings.	150	80
To perform wheel alignment	150	80
To dismantle rear undercarriage	380	60

1410

total: 5322.90
H/S: 4K (Nett Value)

05 Days