

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40160

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0468/2020/NS
Date : 3-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chua Peng Wei Melvin
Address : 69 Jalan Jarak
Singapore 809233
Telephone : HP +65 84532008
Type of Claim : Own Damage Claim
Policy No. : 2070036704
Vehicle No : **SMT 3188 M**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Mar-20
Engine No : CHZ C3564
Chassis No : WAUZZZ8V4LA006297
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Jul-20
Place of Accident : Yio Chu Kang Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMT 3188 M

S/N	Nature of Jobs	S/N	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer both headlights control units and power modules. To carry out calibration.	S/N	\$ 700.00	X.
2	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$	1,050.00 500	
3	To respray front bumper.	\$	900.00 550	
4	To carry out diagnostic check.	S/N	\$ 192.00	✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 2,842.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMT 3188 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Delivered</i>	\$ 1,894.00	✓
2	FRONT BUMPER FIXING PARTS ?	\$ 176.00	?
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>see m</i>	2 \$ 72.00	+
4	FRONT BUMPER GRILLE - CENTRE <i>curled</i>	\$ 151.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>see m</i>	\$ 505.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>see m</i>	2 \$ 560.00	+
7	FRONT BUMPER COVER TRIM - LH / RH <i>see m</i>	2 \$ 306.00	+
8	RADIATOR GRILLE <i>curled</i>	\$ 1,338.00	✓
9	RADIATOR GRILLE CLOSING ELEMENT ?	\$ 180.00	?
10	AIRCON STICKER ? <i>see</i>	NEC \$ 7.00	✓
11	CAUTION SIGN STICKER	NEC \$ 13.00	✓
12	FRONT BUMPER AIR GUIDE GRILLE - LH / RH ?	2 \$ 354.00	?
13	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$ 681.00	?
14	FRONT BUMPER FOAM FILLER PIECE ?	\$ 178.00	?
15	FOAM FILLER PIECE COVER ?	\$ 115.00	?
16	SIGNAL HORN RETAINER - LH HIGH TONE ? <i>see m</i>	\$ 188.00	+
17	SIGNAL HORN RETAINER - RH LOW TONE	\$ 188.00	+
18	LED HEADLIGHT - LH / RH ?	2 \$ 10,386.00	+
19	LIFT CYLINDER - LH / RH <i>see</i>	2 \$ 268.00	+
20	LIFT CYLINDER HOSE <i>see</i>	\$ 64.00	+
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$17,624.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMT 3188 M

S/N	Parts Description	Damage Parts & Prices		
			S/Nett	Remarks
21	RADIATOR AIR GUIDE - LH / RH	2	\$ 46.00	X
22	RADIATOR AIR GUIDE - UPPER CENTRE	\$	12.00	X
23	TEMPERATURE SENSOR BRACKET	\$	18.00	?
24	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓
25	SUNDRIES	\$	300.00	?
TOTAL SPARE PARTS CHARGES		:	\$18,060.00	
TOTAL LABOUR CHARGES		:	\$ 2,842.00	
GRAND TOTAL		:	\$20,902.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Adrian King
08/07/20

Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant