



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

AXA INSURANCE PTE LTD

Ref: CS3/ASM20003122/Hyf3e2

8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 19-03-2020
068811



ATTN : JAS TAN

Code: ASM

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SME 7200M	Veh. Inspected	YP 4367K
Policy No.		Coverage (\$)	0.00
Claim No.	S0M02GO1	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	25/02/2020

2. Vehicle Particulars & Condition


Make & Model	HINO XZU700R	c.c	4009
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JHHTCS3H70K003142	Colour	WHITE
Odometer	197264 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	7.00-16	CASUMINA	5 mm
L/H Front Tyre	7.00-16	CASUMINA	5 mm
R/H Rear Tyre	7.00-16 (D)	KENDA	4/4 mm
L/H Rear Tyre	7.00-16 (D)	KENDA	4/4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.



5. General Information

Accident Date	16/02/2020	Inspect Date / Time	03/03/2020 (11:44 AM)
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,500

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**

Report Ref No. CS3/ASM20003122/Hyf3e2

Inspected By

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.