

INDIA

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Wong Liang Da Lucas

Accident Date : 24-Jun-20

Vehicle No : FBH6416D

Vehicle Model : Honda
CBR600RR

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front signal - L/R/H 155x223/10	\$ CM 340.00 ✓
1	Head lamp assy 485	\$ SCR 650.00 ✓
1	Front fairing	\$ CUY 780.00 ✓
1	Handle bar - R/H	\$ SEL 260.00 ✓
1	Brake pump assy w/brake lever - R/H	\$ CUY 280.00 ✓
1	Throttle cable	\$ CUY 95.00 ✓
1	Mirror - R/H	\$ SCR 165.00 ✓
1	Head lamp side cover - R/H matt blake	\$ CUY 55.00 ✓
1	Front side fairing upper - R/H	\$ CUY 750.00 ✓
1	Front side fairing center - R/H	\$ CUY 650.00 ✓
1	Front side fairing Lower - R/H	\$ CUY 780.00 ✓
1	Rear signal - R/H	\$ SEL 170.00 ✓
1	Rider footrest - R/H	\$ SEL 90.00 X
1	Brake pedal	\$ SEL 160.00 X
1	Pillions footrest - R/H	\$ SEL 90.00 X
1	Pillions footrest bracket - R/H	\$ NY 180.00 X
1	Front side inner cover centre - R/H	\$ NY 55.00 X
1	Rider footrest bracket - R/H	\$ NY 160.00 X
1	Radiator assy	\$ NY 1,050.00 X
1	Front fairing bracket	\$ NY 280.00 X
Less 10%		\$ 7,040.00
		\$ 704.00
		\$ 6,336.00
<u>Special Net Items</u>		
1	Bearing cone	\$ NY 80.00 X
1	Fork repair	\$ NY 120.00 X
		\$ 200.00

not Authorized
2/5 # 4000/
Tuber? H. At the up
4 days
6/7/20
p-4780

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Wong Liang Da Lucas

Accident Date : 24-Jun-20


Vehicle No : FBH6416D

Vehicle Model : Honda
CBR600RR

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service	\$	80.00 ✓
2	To ckeck wiring and reset headlamp focusing	\$ 17	80.00 X
3	To provide labour	\$ 280	480.00
4	To re-spray painting	\$ 400	650.00
		\$	1,290.00
Grand Total		\$	7,826.00
			5062

Singapore Dollars: Seven Thousand Eight Hundred and Twenty-Six only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: