

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
LONPAC INSURANCE BHD			Ref : CS3/LPC20001602/Uvf3e2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date: 15-07-2020 Code: LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBG 9119Y	Veh. Inspected	SJA 6848H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	19/20/20/VC05/022962	Excess (\$)	0.00	
	Assign From	ONG LI LI	Assign Date	06/07/2020	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ C 180 (A)	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	WDD2043312G083135	Colour	GREY	
	Odometer	92997	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/40Z R18	RADAR	6 mm	
	L/H Front Tyre	225/40Z R18	RADAR	6 mm	
	R/H Rear Tyre	225/40Z R18	RADAR	6 mm	
	L/H Rear Tyre	225/40Z R18	RADAR	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	25/01/2020	Inspection Date	30/01/2020	
	Survey held at	62 KAKI BUKIT AVE 6 ARK @ KB 417893			
	Repairer	Repairer ELITES PERFORMANCE			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				