



S THREE AUTOMOTIVE RECOVERY PTE LTD

Not Notified
11 Days?
Recovery After Paint
9 days

TO :
ATTN : MOTOR CLAIM DEPT.

ESTIMATE REPORT 1st QUOTATION
OWNER'S PARTICULAR
NAME : NATIONAL CAR RENTALS PTE LTD
ADDRESS :
LICENSE NO SKQ3306D
MAKE / MODEL : MAZDA CX5
OWNER'S INSURER : NTUC INCOME
JOB-CODE : TP

TRANS. :
S/A : MICHELLE

T/P VEH. NO. :
JOB NO. :
CONTACT : 9471051
CHASSIS NO :
ENGINE NO :
ACCIDENT DATE : 05-10-2019
Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants hence notify
the Repairer as follows:-
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• 9471051 party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

CLAIM DETAIL

MATERIALS

1 FRONT BUMPER
2 FRONT BUMPER FOG LAMP RH
3 FRONT BUMPER FOG LAMP LH
4 FRONT BUMPER FOG LAMP COVER RH
5 FRONT BUMPER FOG LAMP COVER LH
6 FRONT BUMPER RETAINER RH
7 FRONT BUMPER RETAINER LH
8 FRONT BUMPER BRACKET RH
9 FRONT BUMPER BRACKET LH
10 FRONT BUMPER REINFORCEMENT
11 FRONT BUMPER SPONGE
12 FRONT BONNET
13 FRONT BONNET LOCK
14 FRONT BONNET SEAL INNER
15 FRONT BONNET SEAL OUTER
16 FRONT BONNET RUBBER
17 FRONT BONNET HINGE RH
18 FRONT BONNET HINGE LH
19 FRONT GRILLE
20 FRONT GRILLE CHROME
21 FRONT GRILLE LOGO
22 FRONT FENDER PROTECTION RH
23 FRONT FENDER PROTECTION LH
24 FRONT HEADLAMP RH
25 FRONT HEADLAMP LH
26 REAR BUMPER
27 REAR BUMPER TOWING LH
28 REAR BUMPER TOWING RH

QTY	QUO-PRICE	DISC. %	DISC-PRICE	SUR. DISP	REV. PRICE
1.00	Bu 975.00	20.00	780.00	Y	✓
1.00	Bu 352.00	20.00	281.60	Y	X
1.00	Lu 352.00	20.00	281.60	Y	X
1.00	Bu 82.40	20.00	65.92	Y	X
1.00	Lu 82.40	20.00	65.92	Y	X
1.00	Dis 60.00	20.00	48.00	Y	✓
1.00	Dis 60.00	20.00	48.00	Y	✓
1.00	R 60.00	20.00	48.00	Y	X
1.00	R 60.00	20.00	48.00	Y	X
1.00	584.80	20.00	467.84	Y	?
1.00	94.30	20.00	75.44	Y	?
1.00	Bu 1170.00	20.00	936.00	Y	✓
1.00	R 224.00	20.00	179.20	Y	X
1.00	Me 78.00	20.00	62.40	Y	✓
1.00	Lu 28.00	20.00	22.40	Y	✓
1.00	Bu 108.00	20.00	86.40	Y	X
1.00	R 48.00	20.00	38.40	Y	X
1.00	R 48.00	20.00	38.40	Y	X
1.00	682.80	20.00	546.24	Y	?
1.00	CM 288.80	20.00	231.04	Y	✓
1.00	68.00	20.00	54.40	Y	?
1.00	Bu 178.00	20.00	142.40	Y	X
1.00	Lu 178.00	20.00	142.40	Y	X
1.00	995.00	20.00	796.00	Y	?
1.00	995.00	20.00	796.00	Y	?
1.00	Bu 1281.00	20.00	1024.80	Y	✓
1.00	mis 96.00	20.00	76.80	Y	✓
1.00	mis 96.00	20.00	76.80	Y	✓

29	REAR BUMPER LOWER REFLECTOR LH	1.00	CM	186.00	20.00	148.80	Y	✓
30	REAR BUMPER LOWER REFLECTOR RH	1.00	Sn	186.00	20.00	148.80	Y	X
31	REAR BUMPER REINFORCEMENT	1.00		543.00	20.00	434.40	Y	?
32	REAR BUMPER REINFORCEMENT BRACKET LH	1.00		80.00	20.00	64.00	Y	?
33	REAR BUMPER REINFORCEMENT BRACKET RH	1.00		80.00	20.00	64.00	Y	?
34	REAR BUMPER BRACKET LH	1.00		116.00	20.00	92.80	Y	?
35	REAR BUMPER BRACKET RH	1.00		116.00	20.00	92.80	Y	?
36	REAR BUMPER LOWER COVER LH	1.00		220.00	20.00	176.00	Y	?
37	REAR BUMPER LOWER COVER RH	1.00		220.00	20.00	176.00	Y	?
38	REAR BUMPER SIDE RETAINER RH	1.00	Sh	108.00	20.00	86.40	Y	X
39	REAR BUMPER SIDE RETAINER LH	1.00	Dis	108.00	20.00	86.40	Y	✓
40	REAR FENDER PROTECTOR LH	1.00		375.00	20.00	300.00	Y	✓
41	REAR FENDER PROTECTOR RH	1.00	Sn	375.00	20.00	300.00	Y	X
42	REAR END PANEL	1.00	Ry	519.00	20.00	415.20	Y	✓
43	REAR END PANEL INNER TRIM	1.00		134.00	20.00	107.20	Y	?
44	TAILGATE	1.00	Ry	1448.00	20.00	1158.40	Y	✓
45	TAILGATE CATCH	1.00	R	45.60	20.00	36.48	Y	X
46	TAILGATE INNER HANDLE	1.00	Dis	105.00	20.00	84.00	Y	✓
47	TAILGATE OUTER HANDLE	1.00	Sn	105.00	20.00	84.00	Y	X
48	TAILGATE RUBBER BEADING	1.00	Sn	285.60	20.00	228.48	Y	X
49	TAILGATE INNER TRIM	1.00		750.00	20.00	600.00	Y	?
50	TAILGATE LAMP LH	1.00	Sh	495.00	20.00	396.00	Y	X
51	TAILGATE LAMP RH	1.00	Sn	495.00	20.00	396.00	Y	X
52	TAILGATE LOCK	1.00	Red	250.80	20.00	200.64	Y	✓
53	TAILGATE EMBLEM CX5	1.00	Red	42.00	20.00	33.60	Y	✓
54	TAILGATE EMBLEM SKYA CITY	1.00	Red	72.60	20.00	58.08	Y	✓
55	TAILGATE LOGO	1.00	Red	43.60	20.00	34.88	Y	✓
56	TAILGATE DAMPER LH	1.00	Sh	244.00	20.00	195.20	Y	X
57	TAILGATE DAMPER RH	1.00	Sn	244.00	20.00	195.20	Y	X
58	TAILLAMP LH	1.00	Sh	520.00	20.00	416.00	Y	X
59	TAILLAMP RH	1.00	Sn	520.00	20.00	416.00	Y	X
60	REAR NO PLATE LAMP	1.00		42.00	20.00	33.60	Y	?
61	REAR EXHAUST MUFFLER	1.00	Ry	1551.00	20.00	1240.80	Y	✓
62	REAR EXHAUST CHROME 2PCS	1.00	Red	640.00	20.00	512.00	Y	✓
63	REAR EXHAUST CENTRE	1.00		1780.00	20.00	1424.00	Y	?
64	REAR EXHAUST HEAT SHIELD	1.00		269.90	20.00	215.92	Y	?
65	REAR EXHAUST PIPE MOUNTING 4PCS	4.00	Dis	280.00	20.00	224.00	Y	✓
66	REVERSE SENSOR 4PCS	2	CM	1120.00	20.00	896.00	Y	4+
67	REAR AXLE	1.00	Ry	2898.00	20.00	2318.40	Y	✓
68	RADIATOR	1.00	Sn	1012.00	20.00	809.60	Y	X

69 AIR CON CONDENSOR

1.00 1077.00 20.00 861.60 Y

TOTAL (PARTS):

29027.60 23222.08

SPECIAL NETT ITEM

1	FRONT BUMPER CLIPS	1.00	<i>nn</i>	50.00	0.00	50.00	Y	<i>✓</i>
2	FRONT FENDER INNER SHIELD CLIPS	1.00	<i>nn</i>	50.00	0.00	50.00	Y	<i>X</i>
3	FRONT BONNET INSULATOR CLIPS	1.00	<i>nn</i>	80.00	0.00	80.00	Y	<i>X</i>
4	FRONT GRILLE TOP COVER CLIPS	1.00	<i>nn</i>	80.00	0.00	80.00	Y	<i>X</i>
5	FRONT NO PLATE	1.00	<i>By</i>	50.00	0.00	50.00	Y	<i>4500</i>
6	REAR NO PLATE	1.00		50.00	0.00	50.00	Y	
7	REAR BUMPER CLIPS	1.00	<i>nn</i>	80.00	0.00	80.00	Y	<i>✓</i>
8	REAR FENDER PROTECTOR CLIPS	1.00	<i>nn</i>	100.00	0.00	100.00	Y	<i>✓</i>
9	REAR END PANEL SEALANT	1.00	<i>nn</i>	80.00	0.00	80.00	Y	<i>3000</i>
10	REAR EXHAUST MUFFLER MOUNTING	1.00		100.00	0.00	100.00	Y	<i>?</i>
11	REVERSE CAMERA	1.00	<i>nn</i>	680.00	0.00	680.00	Y	<i>X</i>
12	RADIATOR COOLANT	1.00	<i>nn</i>	80.00	0.00	80.00	Y	<i>X</i>

TOTAL (PARTS):

1480.00 1480.00

LABOUR

1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA -FRONT	1.00		1400.00	0.00	1400.00	Y	<i>5000</i>
2	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA -REAR	1.00		1600.00	0.00	1600.00	Y	<i>7000</i>
3	SPRAY PAINTING ON ACCIDENT AREA -FRONT	1.00		1400.00	0.00	1400.00	Y	<i>4000</i>
4	SPRAY PAINTING ON ACCIDENT AREA -REAR	1.00		1400.00	0.00	1400.00	Y	<i>8000</i>
5	RESPRAY TUFF KOTE ON AFFECTED AREA -FRONT	1.00		180.00	0.00	180.00	Y	<i>3000</i>
6	RESPRAY TUFF KOTE ON AFFECTED AREA -REAR	1.00		180.00	0.00	180.00	Y	<i>6000</i>
7	CHECK HEADLAMP WIRING SYSTEM	1.00		180.00	0.00	180.00	Y	<i>2000 2000</i>
8	CONDUCT FULL WHEEL ALIGNMENT	1.00		120.00	0.00	120.00	Y	<i>6000</i>
9	BALANCING TYRES	<i>nn</i> 1.00		80.00	0.00	80.00	Y	<i>X</i>
10	DIAGNOSE, PROGRAME AND RESET ENGINE LIGHT SYSTEM	1.00		380.00	0.00	380.00	Y	<i>?</i>
11	R&R AIR CON CONDENSOR & TOP UP AIR CON GAS R134	<i>nn</i> 1.00		180.00	0.00	180.00	Y	<i>X</i>
12	R&R BOOT INNER TRIM & CARPET TO REPAIR	1.00		120.00	0.00	120.00	Y	<i>6000</i>
13	CHECK TAILLAMP WIRING SYSTEM	1.00		180.00	0.00	180.00	Y	<i>2000</i>
14	R&R EXHAUST MUFFLER PIPE	1.00		280.00	0.00	280.00	Y	<i>1000</i>
15	R&R REVERSE SENSOR & CAMERA SYSTEM	1.00		180.00	0.00	180.00	Y	<i>6000</i>
16	R&R TAILGATE COMPARTMENT AND RESET SYSTEM	1.00		150.00	0.00	150.00	Y	<i>?</i>

TOTAL (LABOUR):

8010.00 8010.00