

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

M/P # 2455-95

NASRUL RIZAL YAHYA
BLK 43 LENGKONG EMPAT
02-01
SINGAPORE 417659
TEL : FAX :
PH : 96656146
ATTN :

Number : EB00005496
Date : 07/07/2020
Case No : AD00011177
Vehicle No : SMQ8591P
Chassis: GK31342709
Year of Mfr 2018
Policy No
Model : HONDA FIT 1.3 GF
 CVT

not Authnt
alt
3/8/20
take the fake pair
4 days.

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	TAILGATE	1.0	420.00	(15)	483.00
2	TAILGATE EMBLEM	1.0	18.00	(15)	20.70
3	TAILGATE LOGO - FIT	1.0	18.00	(15)	20.70
4	TAILGATE TRIMBOARD	1.0	55.00	(15)	63.25
5	TAILLAMP RH	1.0	200.00	(15)	230.00
6	END PANEL	1.0	230.00	(15)	264.50
7	END PANEL TOP GARNISH	1.0	40.00	(15)	46.00
8	REAR FENDER INNER TRIMBOARD RH	1.0	150.00	(15)	172.50
9	REAR BUMPER	1.0	200.00	(15)	230.00
10	REAR BUMPER RETAINER RH	1.0	12.00	(15)	13.80
11	REAR BUMPER RETAINER LH	1.0	12.00	(15)	13.80
12	REAR BUMPER LOWER CENTER SPOILER	1.0	45.00	(15)	51.75
13	TAILGATE WINDSCREEN MOULDING	1.0	70.00	(15)	80.50
14	TAILGATE OUTER GARNISH	1.0	130.00	(15)	149.50
15	REAR REFLECTOR LAMP RH	1.0	70.00	(15)	80.50
16	TAILGATE LOCK	1.0	75.00	(15)	86.25
17	TAILGATE RUBBER	1.0	45.00	(15)	51.75
Nett Price - Parts Sub Total					2,058.50
18	REVERSE SENSOR	1.0	280.00	0	280.00
19	WINDSCREEN SEALANT	2.0	24.00	0	48.00
20	REAR FENDER RH - REPAIR	1.0			
21	SPARE TYRE PANEL - REPAIR	1.0			
Special Nett Price - Parts Sub Total					328.00
Parts Total					2,386.50
22	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	800.00	0	800.00
23	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
24	ANTI-RUST COATING	1.0	120.00	0	120.00
25	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
26	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					2,050.00

LKK Auto Consultants hence notify
the Repairer of the following:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HOCK WAH MOTOR WORKSHOP PTE LTD

Acknowledged by Repairer
Signature: _____
Date: _____

AUTHORISED SIGNATURE

Page 1 of 2

* N = Item not subjected to GST

Issued by : Anysia

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXXX308Z
NASRUL RIZAL YAHYA
BLK 43 LENGKONG EMPAT
02-01
SINGAPORE 417659
TEL : FAX :
PH : 96656146
ATTN :

ESTIMATE BILL

Number : EB00005496
Date : 07/07/2020
Case No : AD00011177
Vehicle No : SMQ8591P
Chassis: GK31342709
Year of Mfr 2018
Policy No
Model : HONDA FIT 1.3 GF
CVT

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
SINGAPORE DOLLARS : FOUR THOUSAND SEVEN HUNDRED FORTY-SEVEN AND CENTS SIX ONLY			Less Excess		0.00
			SUBTOTAL		4,436.50
			GST 7.00%		310.56
			TOTAL		4,747.06

Date of accident : 06/07/2020 05:50 PM. Place : TRAFFIC JUNC OF JALAN KEMBANGAN > SIMS AVE EAST

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 8781 / 6746 8638



Dept Direct: 6417 8784

Dept Direct: 6417 8786

Dept Direct: 6417 8788

Dept Direct: 6417 8789

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

HOCK WAH MOTOR WORKSHOP PTE LTD

3011 BEDOK INDS PARK E

#01-2008

[NEED PO]

SINGAPORE 489977

TEL : 64415655 FAX : 62438121

ATTN : (SMALL ITEM PASS TO COUNTER) GUAN 98633934

TAX INVOICE : AR202008-01503

DATE : 04/08/2020

CUSTOMER ID : HOC001

VEH REG. NO. : SMQ8591P

TERMS : 30 days

PO NO. : 35305

PAGE NO. : Page 1 of 1

CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	H68100-T5L-Z00ZZ GK3	TAILGATE ASSY	WH HL1-F2	1	420.00	420.00
2.	H75722-T5A-003 GK3	"FIT " EMBLEM	WH HL2-E20-C	1	18.00	18.00
3.	H71501-T5L-T50ZZ GK3 NEW	BUMPER RR	WH HL2-M16	1	200.00	200.00
4.	H71505-T5A-J50 GK3 GP5 2018	GARNISH, RR. BUMPER CENTER	WH HL2-P10	1	45.00	45.00
5.	H73226-SZW-000 GK3 FIT / RC1 ODY 14"/RM3	H73226-SZW-000 RR GLASS TOP MLD	WH 1HSD	4	17.50	70.00

SUB-TOTAL : 753.00

ADD GST 7.00 % 52.71

E. & O.E

TOTAL AMOUNT SGD : 805.71

[P] 04/08/2020 5:54:20PM

[E] 04/08/2020 5:50:08PM


Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : EDMUND



* A R 2 0 2 0 0 8 - 0 1 5 0 3 *

This is computer generated document.

No signature is required.

ORIGINAL

Signature / Co Stamp / Date