



BAN HOCK HIN
Co., Pte Ltd

Co Reg No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

Customer: *Steve CLKK*
MISCELLANEOUS CUSTOMER

ATTN: MUHAMMAD BIN NASIR BAEESA

TEL :
FAX :

VEHICLE NO. : FBM3733G
MAKE MODEL : K.T.M - K.T.M 125 DUKE

Authn
00 - *36319*

Excpn - ?

P/P

By BPL Sy
3 dgs

8/7/10, 12.00pm

QUOTATION

NO. : 36319


DATE : 07/07/2020
JOB NO. : DLJB40260812
FROM : SHIWEI

MILEAGE: 35840

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE REAR Stock Availability (Days): 1 <i>✓ CUT</i>	REPLACE	1.00	\$52.00	\$52.00 ✓
2	BAR HANDLE Stock Availability (Days): 1 <i>✓ BT</i>	REPLACE	1.00	\$140.00	\$140.00 ✓
3	BOX REAR (KAPPA) K-VENTURE 42L P.N: 57761 Stock Availability (Days): 1 <i>✓ NN</i>	REPLACE	1.00	\$568.00	\$568.00 ✓
4	BRACKET BOX REAR (GIVI) 7707FZ Stock Availability (Days): 90 <i>✓ NN</i>	REPLACE	1.00	\$127.00	\$127.00 ✓
5	BRACKET FOOTREST REAR LH Stock Availability (Days): 1 <i>✓ CUT</i>	REPLACE	1.00	\$72.00	\$72.00 ✓
6	BRAKE LEVER Stock Availability (Days): 1 <i>✓ BT</i>	REPLACE	1.00	\$35.00	\$35.00 ✓
7	COVER TANK SIDE LH ORANGE Stock Availability (Days): 1 <i>✓ OR</i>	REPLACE	1.00	\$105.00	\$105.00 ✓
8	COVER TANK SIDE RH ORANGE Stock Availability (Days): 1 <i>✓ OR</i>	REPLACE	1.00	\$105.00	\$105.00 ✓
9	FOOTREST REAR LH ASSY Stock Availability (Days): 1 <i>✓ CUT</i>	REPLACE	1.00	\$35.00	\$35.00 ✓
10	GUARD ENGINE (ORANGE) Stock Availability (Days): 1 <i>✓ BT</i>	REPLACE	1.00	\$377.00	\$377.00 ✓
11	GUARD HANDLE Stock Availability (Days): 1 <i>✓ BR</i>	REPLACE	1.00	\$316.00	\$316.00 ✓
12	LEVER CLUTCH Stock Availability (Days): 1 <i>✓ BR</i>	REPLACE	1.00	\$38.00	\$38.00 ✓
13	MIRROR LH Stock Availability (Days): 1 <i>✓ CY</i>	REPLACE	1.00	\$35.00	\$35.00 ✓

bizSAFE



Address: No. 6, Bala Jang, Singapore 336118 | Telephone: +65 6261 6520 | Web: www.bh.com.sg
Fax: (Main) +65 6261 2630, (Sales Dept) +65 6265 7530, (Customer P/ty) +65 6264 2900, (Accounts) +65 6261 8750

S/N	Description	Action	Qty	Unit Price	Amount
14	MIRROR RH Stock Availability (Days): 1	REPLACE	1.00	\$35.00	\$35.00 ✓
15	MUFFLER ASSY Stock Availability (Days): 1	REPLACE	1.00	\$463.00	\$463.00 ✓
16	PEDAL GEAR Stock Availability (Days): 1	REPLACE	1.00	\$52.00	\$52.00 ✓
17	PIN 25X1.8MM P/N: 57757 Stock Availability (Days): 1	REPLACE	1.00	\$1.60	\$1.60 ✓
18	PLATE FOOTREST LOCK 1 Stock Availability (Days): 1	REPLACE	1.00	\$4.30	\$4.30 ✓
19	PLATE FOOTREST LOCK 2 Stock Availability (Days): 1	REPLACE	1.00	\$4.30	\$4.30 ✓
20	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 Stock Availability (Days): 1	REPLACE	1.00	\$21.00	\$21.00 ✓
21	SIGNAL REAR LH ASSY Stock Availability (Days): 1	REPLACE	1.00	\$56.00	\$56.00 ✓
22	SPECIAL SCREW M6X1X10 Stock Availability (Days): 1	REPLACE	1.00	\$24.00	\$24.00 X
23	STICKER RH LED ORANGE Stock Availability (Days): 1	REPLACE	1.00	\$51.00	\$51.00 ✓
24	STICKER SET FOR DUKE125 ORANGE Stock Availability (Days): 1	REPLACE	1.00	\$103.00	\$103.00 ✓
25	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	8.00	\$45.00	\$360.00
SUB TOTAL				1891.98	\$3,180.20
GST @ 7 %					\$222.61
GRAND TOTAL					\$3,402.81

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



SHIWEI

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

bizSAFE₃