

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMP1315Y (Insd veh)	Model:	TOYOTA HIACE 3.0 D TURBO 5
	4948S,GBF9492Z (TP veh)		DR (M)
Date of Accident:	27/06/2020		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	35,976.05
Final Repair Cost	:	\$	13,910.00
Loss of Use	:	\$	1,120.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	15,030.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Lee Sheng Auto Pte Ltd	:	\$ 15,030.00
2)		:	\$

JOANNE LEE KHANG MIN

24 Mar
2021

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))