

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

SOMPO INSURANCE SINGAPORE PL CS3/SMO20007088/Uyf3e2

50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623

Code: SMO

16-07-2020 Date:

Page No.:1 of 1

			Code: SMO				
1. Policy Particulars :- (THIRD PARTY CLAIM)							
Ins	sured Veh.	FBQ 1048T	Veh. Inspected	FBQ 7417Y			
Po	licy No.		Coverage (\$)	0.00			
Cla	aim No.	CMTD2002003/AGC	Excess (\$)	0.00			
As	sign From	GRACE TEO	Assign Date	07/07/2020			
2. Vehicle Particulars & Condition							
Ma	ike & Model	YAMAHA MTN155	c.c	155			
En	gine No.	HIDDEN	Year of Reg.	2019			
Ch	assis No.	MH3RG5620K0004279	Colour	BLUE			
Od	lometer	10167 KM	Steering	IN ORDER			
Br	akes	IN ORDER	Modification	SPORTS RIM			
Ge	neral	GOOD					
3. Conditions of Tyres							
		Size	Make	Balance			
R/I	H Front Tyre	110-70 R17	PIRELLI	6 mm			
L/ŀ	H Front Tyre			mm			
R/I	H Rear Tyre	140-70 R17	PIRELLI	6 mm			
L/ŀ	H Rear Tyre			mm			
	Description of Damages						
T⊔	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND PEAR PORTION						

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND REAR PORTION.



5.	General Information					
	Accident Date	03/07/2020	Inspect Date / Time	08/07/2020 ( 09:20 AM )		
	Survey held at	AH FOOK MOTOR-5 SOON LEE STREET #01-15				
	Repairer	-				

5a. **Remarks** 

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
- D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500

5b. **Estimate Days of Repair** 

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

Report Ref No. CS3/SMO20007088/Uyf3e2

Inspected By

**CHUA KANG SENG** 

K.K.LAU CPT(RET)

**Licensed Appraiser** 

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.