

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 40144

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0467/2020/NS
Date	:	3-Jul-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	ERBE Singapore Pte Ltd
Address	:	25 International Business Park #02-55/56 Singapore 609916
Telephone	:	+(HP) 97537561
Type of Claim	:	Own Damage Claim
Policy No.	:	1800120277-01
Vehicle No	:	SME 8293 M
Model Code	:	Audi Q5 2.0 TFSI qu
Model / Year	:	Oct-18
Engine No	:	DAX 041384
Chassis No	:	WAUZZZF2J2197223
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	2-Jul-20
Place of Accident	:	CTE (AMK Ave 3/5 Exit)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 8293 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$ 280.00	/ /
2	To remove and transfer lhs headlight control units and power modules. To carry out calibration.	S/N \$ 400.00	X NN
3	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00	500 /
4	To respray front bumper, front bumper lower spoiler and both front wheel arch trims.	\$ 3,000.00	950 1500
5	To carry out diagnostic check.	S/N \$ 192.00	/ /
TOTAL LABOUR CHARGES		: \$ 5,072.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8293 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>de</i> ✓	\$ 2,473.00	1978.40
2	FRONT BUMPER FIXING PARTS <i>? xsv</i>	\$ 254.00	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>? xsv</i>	\$ 212.00	
4	FRONT BUMPER GRILLE - CENTRE <i>X svc</i>	\$ 135.00	
5	FRONT SPOILER <i>2 cr</i> ✓	\$ 717.00	573.20
6	FRONT BUMPER UNDERRUN BAR <i>2 cut</i> ✓	\$ 452.00	361.60
7	FRONT BUMPER CLOSING ELEMENT <i>2 de</i> ✓	\$ 163.00	130.40
8	RADIATOR GRILLE <i>cut</i> ✓	\$ 3,327.00	2661.60
9	QUATTRO INSCRIPTION <i>new</i> ✓	\$ 90.00	71.76
10	STRIKER PLATE <i>? xsv</i> <i>sv</i> <i>X cut</i> ✓	\$ 230.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>21</i> <i>X</i> ✓	\$ 1,090.00	436.00
12	FRONT BUMPER END CAP - LH / RH <i>X svc</i>	2 \$ 174.00	
13	LOCKING CLIP <i>X svc</i>	4 \$ 15.00	
14	FRONT BUMPER CARRIER <i>? xsv</i>	\$ 868.00	
15	FRONT BUMPER FOAM FILLER PIECE <i>? cr</i> ✓	\$ 272.00	217.20
16	FOAM FILLER PIECE COVER <i>? xsv</i>	\$ 121.00	
17	CAUTION SIGN STICKER <i>X nn</i>	NEC \$ 13.00	
18	AIRCON STICKER <i>X nn</i>	NEC \$ 18.00	
19	FRONT PARKING AID SENSOR - INNER / OUTER <i>X svc</i>	2 TBC	
20	FRONT PARKING AID SEAL RING <i>new X nn</i>	4 \$ 14.00	
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 10,638.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8293 M

S/N Parts Description		Damage Parts & Prices		Remarks
		S/Nett		
21	FRONT WHEEL COVER - LH / RH <i>Free</i> ✓	2	\$ 1,190.00	952
22	RADIATOR AIR GUIDE - LH / RH <i>X sue</i>	2	\$ 110.00	
23	RADIATOR AIR GUIDE - CENTRE <i>X sue</i>		\$ 40.00	
24	RADIATOR AIR GUIDE - LOWER <i>X sue</i> / SVC		\$ 45.00	
25	HEADLIGHT MOUNTING - LH <i>? con</i> ✓		\$ 112.00	89.20
26	LED HEADLIGHT - LH <i>? X sue</i>		\$ 7,555.00	
27	LIFT CYLINDER - LH / RH <i>X sue</i>	2	\$ 264.00	
28	FRONT NO PLATE <i>bt</i> ✓	S/N	\$ 60.00	✓
29	SUNDRIES <i>? X sue</i>		\$ 300.00	
TOTAL SPARE PARTS CHARGES		:	\$20,314.00	
TOTAL LABOUR CHARGES		:	\$ 5,072.00	
GRAND TOTAL		:	\$25,386.00	25,656.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : RASUL - HP 90010068
Surveyed Date : 07/07/2020 @ 1320
Authorised Date :
Excess Cost : 3 days
Liability : EXCESS: TBA
Remarks : REPAIR
Resurvey before paint

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0467/2020/NS

20-Jul-20

Glory Tan

1 OF 1

SME 8293 M

Audi Q5 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
Parts			
1	Wheel spoiler RHS <i>com</i>	\$ 153.00	122.40
2	Headlight mounting RHS <i>com</i>	\$ 117.00	93.60
TOTAL		\$ 270.00	

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rane
21/07/2020

Authorised Signature

*Subject to
insurance approval*