

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0467/2020/NS

Date

20-Jul-20

Service Advisor

Glory Tan

Pages

1 OF 1

Regn No

SME 8293 M

Model No

Audi Q5 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Wheel spoiler RHS <i>com</i>	\$ 153.00	
2	Headlight mounting RHS <i>com</i>	\$ 117.00	
TOTAL		\$ 270.00	

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rane
21/07/2020

Authorised Signature

Subject to
insurance approval

Car-in

20/7/2020.

L2 / Hlong - AIG Reclaim

wip: 40144

3 bays

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8293 M

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>de</i>	\$ 2,473.00	
2	FRONT BUMPER FIXING PARTS ?	\$ 254.00	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH ?	2 \$ 212.00	
4	FRONT BUMPER GRILLE - CENTRE X NN	\$ 135.00	
* 5	FRONT SPOILER <i>cut</i>	\$ 717.00	
6	FRONT BUMPER UNDERRUN BAR <i>cut</i>	\$ 452.00	
* 7	FRONT BUMPER CLOSING ELEMENT <i>de</i>	\$ 163.00	
8	RADIATOR GRILLE <i>cut</i>	\$ 3,327.00	
9	QUATTRO INSCRIPTION <i>re</i>	\$ 90.00	
10	STRIKER PLATE ? NN	\$ 230.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>cut</i>	21 \$ 1,090.00	
12	FRONT BUMPER END CAP - LH / RH X NN	2 \$ 174.00	
13	LOCKING CLIP X NN	4 \$ 15.00	
14	FRONT BUMPER CARRIER ?	\$ 868.00	
* 15	FRONT BUMPER FOAM FILLER PIECE <i>cut</i>	\$ 272.00	
16	FOAM FILLER PIECE COVER ?	\$ 121.00	
17	CAUTION SIGN STICKER X NN	NEC \$ 13.00	
18	AIRCON STICKER X NN	NN NEC \$ 18.00	
19	FRONT PARKING AID SENSOR - INNER / OUTER X	2 TBC	
20	FRONT PARKING AID SEAL RING <i>re</i>	4 \$ 14.00	
SUB TOTAL SPARE PARTS CHARGES		: <u>\$ 10,638.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 8293 M

S/N Parts Description		Damage Parts & Prices		Remarks
		S/Nett		
21	FRONT WHEEL COVER - LH / RH <i>free</i> ✓	2	\$	1,190.00
22	RADIATOR AIR GUIDE - LH / RH X NN	2	\$	110.00
23	RADIATOR AIR GUIDE - CENTRE X NN		\$	40.00
24	RADIATOR AIR GUIDE - LOWER X NN		\$	45.00
* 25	HEADLIGHT MOUNTING - LH ? <i>free</i> ✓		\$	112.00
26	LED HEADLIGHT - LH ?		\$	7,555.00
27	LIFT CYLINDER - LH / RH X NN	2	\$	264.00
28	FRONT NO PLATE <i>bt</i> ✓	S/N	\$	60.00
29	SUNDRIES ?		\$	300.00
TOTAL SPARE PARTS CHARGES		:		\$20,314.00
TOTAL LABOUR CHARGES		:		\$ 5,072.00
GRAND TOTAL		:		<u>\$25,386.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Headlight mounting RH
wheel spoiler RHS

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 8293 M

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$ 280.00 /	
2	To remove and transfer lhs headlight control units and power modules. To carry out calibration.	S/N \$ 400.00 /	X NN
3	To dismantle and renew front bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00	500
4	To respray front bumper, front bumper lower spoiler and both front wheel arch trims.	\$ 3,000.00	950 + 550 = 1500
5	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: \$ 5,072.00	