



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SM AUTOMOTIVE

Ref : CS/TP20007107/Aqf3e2

1 KAKI BUKIT AVENUE 6
BLOCK D AUTOBAY #01-43
SINGAPORE 417883

Date : 01-10-2020



ON BEHALF OF TLT TRANSPORTATION PTE LTD Code : TP440

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	YN 4012U
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	04/07/2020

2. Vehicle Particulars & Condition

Make & Model	UD TRUCKS MKB8ELNHAA	c.c	7013
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	MKB8E00148	Colour	WHITE
Odometer	253355	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/75 R17.50	FIRENZA	6 mm
L/H Front Tyre	235/75 R17.50	FIRENZA	6 mm
R/H Rear Tyre	235/75 R17.50 (D)	BOTO	6/6 mm
L/H Rear Tyre	235/75 R17.50 (D)	BOTO	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/06/2020	Inspection Date	04/07/2020
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	24 Working Days
-------------------------------------	-----------------