



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20007117/QUtf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 23-09-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 9118U	Veh. Inspected	SJV 2201P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002036/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	08/07/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA STREAM 1.8L	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	JHMRN68809C200455	Colour	GREY
Odometer	123556	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R18	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R18	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/07/2020	Inspection Date	08/07/2020
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
--	-----------------------