



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS3/FCI18016377/Gvf3s2-1

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 09-07-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3076X	Veh. Inspected	SLZ 4879B
Policy No.		Coverage (\$)	0.00
Claim No.	D18006658MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	26/06/2020

2. Vehicle Particulars & Condition

Make & Model	SKODA SUPERB	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	TMBBB93T699038418	Colour	BROWN
Odometer	143609	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/35ZR19	DURUN	6 mm
L/H Front Tyre	235/35ZR19	DURUN	6 mm
R/H Rear Tyre	235/35ZR19	THUNDERER	6 mm
L/H Rear Tyre	235/35ZR19	RHINO PLUS	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/09/2018	Inspection Date	10/09/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------