

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Veron

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0481/2020/NS 13-Jul-20 Glory Tan 1 of 1 SKG 1989 Z Audi A5 Sportsback 2.0 TFSI Qu
--	---	--

Quantity	Description	Unit Price	Amount
Parts			
1	Front fender emblem trim RHS <i>new</i>	\$ 150.00	150.00 125.60
2	Bracket lock carrier <i>could</i>	\$ 129.00	129.00 108.40
Labours			
1	To repair rhs front fender.	\$ 800.00	250 ✓
2	To respray rhs front fender.	\$ 1,000.00	550 ✓
3	To repair rhs upper A-pillar.	\$ 800.00	250 ✓
4	To respray rhs upper A-pillar.	\$ 1,000.00	550 ✓
TOTAL		\$ 1,800.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Lj
13/07/20
fly add 3 days