

Chino-FJM (45)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 08.07.2020

Time: 09:49:53

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305409755  
REGN NO : SHC8736Y  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 21.01.2016  
DATE/TIME IN : 08.07.2020 08:15  
ACCIDENT DATE : 07.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1	1,106.00	20.00	884.80	Rp	
0002	04-01-0103-0574-G	I40VC PANEL-FENDER LH#	1	2,171.40	20.00	1,737.12	Rp	
0003	04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	107.10	20.00	85.68	cut ✓	85.68
							SUB-TOTAL :	2,707.60

JOB NATURE

0000	PB	PANEL BEATING		840.00		420		
0001	SP	SPRAYPAINT CHARGE		500.00		400		
0002	17-01	CHECK ALL LIGHTING		50.00		30		
0003	20-00	TUFF COAT ON AFFECTED PARTS.				30.00	✓	
0004	20-05	RENEW ADVERTISEMENT STICKER-		200.00		1080	✓ net ✓	
							SUB-TOTAL :	1,620.00

Tanjin 97495714  
8/7/20 @ 4 pm  
Lumpsum  
Resurvey after repair.  
Tanjin @ Insurance.com  
• 2-3 days

85.68  
1080  
1165.68  
1/3 @ 950  
2 days \*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: