



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

CHIN MENG MOTORS

Ref : CS/TP20007176/Ayf3e2

1 KAKI BUKIT AVE 6  
#01-40/63 SINGAPORE 417883

Date : 23-07-2020



ON BEHALF OF CERTIS CISCO AUXILIARY  
POLICE FORCE PTE LTD

Code : TP171

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	RU 6857G
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	08/07/2020

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA HIACE	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTFHT02P500242200	Colour	WHITE
Odometer	143659	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	DUNLOP	6 mm
L/H Front Tyre	195 R15C	DUNLOP	6 mm
R/H Rear Tyre	195 R15C	DUNLOP	6 mm
L/H Rear Tyre	195 R15C	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	26/06/2020	Inspection Date	08/07/2020
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------