

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 9-Jul-20

INSURANCE: AIG

MODEL: TOYOTA PRIUS

VEHICLE NO.: SHD7295D

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR BUMPER <i>Cut</i>	1	\$458.60	\$458.60	✓
REAR BUMPER RE-INFORCEMENT <i>NH</i>	1	\$318.80	\$318.80	X
REAR BUMPER LOWER COVER <i>NH</i>	1	\$552.60	\$552.60	X
REAR BUMPER SIDE RETAINER <i>SVL</i>	1	\$112.70	\$112.70	X
REAR BUMPER CLIPS <i>NH</i>	1	\$22.00	\$22.00	✓
REAR BUMPER UPPER STOPPER (RH) <i>NH</i>	1	\$76.40	\$76.40	X
ARM SUB-ASSY, REAR BUMPER, RH <i>Cut NH</i>	1	\$139.60	\$139.60	X
REAR BUMPER UNDER SIDE COVER (RH) <i>NH</i>	1	\$232.00	\$232.00	X
SEAL, REAR BUMPER SIDE, RH <i>Cut</i>	1	\$148.40	\$148.40	✓
REAR FENDER, RH <i>Debris</i>	1	\$836.70	\$836.70	✓
REAR FENDER OUTER PANEL, RH <i>NH</i>	1	\$486.00	\$486.00	X
REAR FLOOR PANEL SIDE (RH) <i>NH</i>	1	\$276.20	\$276.20	X
REAR FENDER SHIELD (RH) <i>SVL</i>	1	\$174.20	\$174.20	X
REAR FENDER AIR DUCT <i>NH</i>	1	\$165.10	\$165.10	X
REAR FLOOR PANEL SIDE (RH) <i>NH</i>	1	\$717.60	\$717.60	X
REAR FLOOR BOARD ((RH) <i>NH</i>	1	\$823.40	\$823.40	X
REAR FLOOR UNDER COVER (RH) <i>NH</i>	1	\$846.80	\$846.80	X
PANEL SUB-ASSY, REAR DOOR, RH <i>Debris</i>	1	\$1,258.30	\$1,258.30	✓
REAR DOOR HINGE UPPER <i>NH</i>	1	\$82.30	\$82.30	X
REAR DOOR HINGE LOWER <i>NH</i>	1	\$82.30	\$82.30	X
REAR DOOR CHECK <i>NH</i>	1	\$153.00	\$153.00	X
REAR DOOR TRIMBOARD <i>NH</i>	1	\$725.00	\$725.00	X
PANEL SUB-ASSY, FRONT DOOR, RH <i>Debris</i>	1	\$1,264.00	\$1,264.00	✓
FRONT DOOR COMFORT LOGO <i>NH</i>	1 <i>SH</i>	\$75.00	\$75.00	✓
Rocker Panel Outer Garnish <i>Cut / broken</i>	1	\$576.00	\$576.00	✓
Rocker Panel Outer <i>NH</i>	1	\$519.80	\$519.80	X
Rocker Panel Step Garnish(Rear)(RH) <i>NH</i>	1	\$ 178.30	\$178.30	X
REAR TYRE (RH) <i>NH</i>	1	\$216.00	\$216.00	X
REAR TYRE RIM (RH) <i>Cut / Debris</i>	1	\$1,555.00	\$1,555.00	✓
REAR WHEEL HUB CAP (RH) <i>NH</i>	1	\$177.70	\$177.70	X
REAR WHEEL BEARING & HUB assy <i>2 Debris</i>	1	\$610.20	\$610.20	✓
REAR SHOCK ABSORBER <i>2 disturbed</i>	1	\$118.30	\$118.30	✓
REAR SHOCK ABSORBER MOUNTING <i>NH</i>	1	\$125.30	\$125.30	X
REAR LOWER ARM <i>2 disturbed</i>	1	\$497.50	\$497.50	✓
REAR UPPER ARM <i>2 disturbed</i>	1	\$356.80	\$356.80	✓
REAR KNUCKLE ARM <i>2 disturbed</i>	1	\$810.60	\$810.60	✓
REAR COIL SPRING <i>NH</i>	1	\$191.40	\$191.40	X
REAR COIL SPRING MOUNTING <i>NH</i>	1	\$125.70	\$125.70	X
REAR BRAKE ABS SENSOR (WIRE) <i>NH</i>	1	\$278.80	\$278.80	X
REAR STABILIZER BAR <i>NH</i>	1	\$311.50	\$311.50	X
REAR STABILIZER LINK <i>NH</i>	1	\$151.60	\$151.60	X

REAR TRAILING ARM <i>2 distorts</i>	1	\$314.20	\$314.20	<i>21 ✓</i>
REAR ASSIST ARM <i>2 distorts</i>	1	\$342.20	\$342.20	<i>21 ✓</i>
REAR HEIGHT SENSOR LH only <i>HH</i>	1	\$789.30	\$789.30	<i>X</i>
SUB TOTAL			\$18,273.20	
LESS 20% <i>25%</i>			\$3,654.64	
DISCOUNTED TOTAL			\$14,618.56	
REAR DOOR COMFORT & APPS STICKER <i>Hec</i> SN	1	\$80.00	\$80.00	<i>✓</i>
SUB TOTAL			\$80.00	
Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	<i>900/-</i>
Spray Painting Charge	1	\$1,200.00	\$1,200.00	<i>800/-</i>
Wiring Charge	1	\$160.00	\$160.00	<i>HH</i>
Tuff Kote	1	\$140.00	\$140.00	<i>40/-</i>
Towing Charge	1	\$80.00	\$80.00	<i>HH</i>
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	<i>80/-</i>
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00	<i>180/-</i>
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00	<i>60/-</i>
Re-set Frt Power Window System	1	\$200.00	\$200.00	<i>HH</i>
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00	<i>60/-</i>
Re-set Rear Power Window System	1	\$200.00	\$200.00	<i>HH</i>
Four Wheel Alignment	1	\$120.00	\$120.00	<i>60/-</i>
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	<i>150/-</i>
TOTAL LABOUR			\$4,760.00	
ESTIMATE TOTAL			\$19,458.56	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

13/07/2020 e 1700hrs

NA Andrew Peathy PCA.

Tyler Edg.

LKK Auto

[Signature]

Photo after repair with damaged parts.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: