

SJJ3065Y
TP/AIG

Cheng Hoe Motor Pte Ltd

BL 1019, Yohin Industrial Park A #01-374/382, Singapore 768761
TEL: 6756142 (YS) FAX: 67557119 (YS) Email: chmoter@chenghoe.com.sg
GST: 20100115SE BCB NO: 20100115SE

Not Withheld
U/Pay 8?
Money After Rain
Today

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Claim No: ESTIMATE
Estimate No: ESTIMATE
Date: 17-Jul-20
Policy No: DMPCNSA00021892001
Veh Reg No: SJJ3065Y
Make/Model: HONDA STREAM 1.8X A

WS Ref: TP/AIG
Claim Type: TP CLAIM
Accident Date: 09/07/2020
TP Veh Reg No: EQ699K

Chassis No: RN61082892
Engine No: R18A1792020
Reg. Date: 08/09/2008

Estimate Repair Cost to Vehicle : SJJ3065Y

Description	U/Price	Quantity	Amount
List	SS	Bt / CM	
1 FRT BUMPER		1 PC	793.10 ✓
2 FRT BUMPER REINFORCEMENT		1 PC <i>As</i>	218.50 ✓
3 FRT BUMPER LH SIDE RETAINER		1 PC <i>CM</i>	19.80 ✓
4 FRT BUMPER CLIPS @ 3.50/PC		6 PCS <i>As</i>	21.00 ✓
5 FRT BUMPER LH FOG LAMP GARNISH		1 PC	22.80 ✓
6 FRT LH FENDER		1 PC <i>As</i>	539.20 ✓
7 FRT LH FENDER INNER SHIELD		1 PC <i>CM</i>	118.90 ✓
8 FRT LH FENDER INNER SHIELD CLIPS @ 3.50/PC		6 PCS <i>As</i>	21.00 ✓
9 LH HEADLAMP 'HID'		1 PC	927.10 ✓
10 LH HEADLAMP LOWER RETAINER		1 PC <i>CM</i>	36.50 ✓
11 FRT GRILLE		1 PC	289.10 ✓
12 FRT GRILLE CLIPS @ 3.50/PC		4 PCS	14.00 ✓
13 AIR FILTER RESONATOR		1 PC <i>As</i>	198.90 ✓
14 FRT LH FENDER INNER PANEL		1 PC	389.10 ✓
15 BONNET		1 PC <i>As</i>	638.90 ✓
			4247.90
	Less 20%		849.58 3398.32
Labour			
16 REMOVE & REFIX FRT BUMPER ASSY, HEADLAMPS, FRT GRILLE, FRT FENDERS, BONNET & ATTACHMENT, KNOCK & REPAIR FRT SUPPORT PANEL, CUT, WELD, RENEW FRT LH FENDER INNER PANEL & REALIGN THE SAME			800.00 <i>650</i>
17 PUTTY & RESPRAY FRT LH DOOR, FRT BUMPER, REINFORCEMENT, SUPPORT PANEL, FRT LH FENDER, FRT LH FENDER INNER PANEL, BONNET			1100.00 <i>1000</i>
18 REMOVE & REFIX FRT LH SPORT RIM, REPAIR, SPRAY AND BALANCING			80.00 <i>60</i>
19 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT			60.00 ✓
20 RUSTPROOFING			60.00 ✓
			2100.00
		TOTAL	5498.32
		Add GST 7%	384.88
		GRAND TOTAL	5883.20

LKCAuto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: