

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2007-088

DATE : 9-Jul-2020

POLICY NO. : FWD PNPV2020-00005998

VEHICLE REG. NO. : SML4183L

VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A) S

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Bumper	1	\$ 500.00	\$ 500.00
2	Front Bumper Clip	10	\$ 3.00	\$ 30.00
3	Front Bumper Retainer LH	1	\$ 30.00	\$ 30.00
4	Front Bumper Upper Support Bracket LH - 86554B	1	\$ 30.00	\$ 30.00
5	Front Bumper Side Grille LH - 86512L	1	\$ 50.00	\$ 50.00
6	Front Bumper Lower Moulding LH - 86571P	1	\$ 50.00	\$ 50.00
7	Front Bumper Fog lamp LH - 92302A	1	\$ 200.00	\$ 200.00
8	Front Air Curtain Duct LH - 86567E	1	\$ 30.00	\$ 30.00
9	Front Bumper Under Lip Assy - 86590E	1	\$ 90.00	\$ 90.00
10	Front Bumper Under Cover	1	\$ 150.00	\$ 150.00
11	Front Bumper Under Cover Clip	10	\$ 3.00	\$ 30.00
12	Front Reinforcement	1	\$ 700.00	\$ 700.00
13	Front Sponge/absorber	1	\$ 120.00	\$ 120.00
14	Front Grille Assy	1	\$ 480.00	\$ 480.00
15	Front Headlamp LH	1	\$ 1,800.00	\$ 1,800.00
16	Front Headlamp Bracket LH	1	\$ 30.00	\$ 30.00
17	Front Fender LH	1	\$ 980.00	\$ 980.00
18	Front Fender Shield LH	1	\$ 90.00	\$ 90.00
19	Front Fender Clip	10	\$ 3.00	\$ 30.00
20	Support Panel	1	\$ 980.00	\$ 980.00
21	Front Buzzer Assy	1	\$ 80.00	\$ 80.00
22	Front Knuckle LH	1	\$ 380.00	\$ 380.00
23	Front Bearing & Wheel Hub LH	1	\$ 120.00	\$ 120.00
24	Front Tie Rod LH	1	\$ 120.00	\$ 120.00
25	Front Tie Rod End LH	1	\$ 100.00	\$ 100.00
26	Front Absorber LH	1	\$ 300.00	\$ 300.00
27	Front Lower Arm LH	1	\$ 300.00	\$ 300.00
28	Front Stabiliser	1	\$ 220.00	\$ 220.00
29	Front Stabiliser Linkage LH	1	\$ 80.00	\$ 80.00
30	Hyundai Rim R16	1	\$ 900.00	\$ 900.00
31	Front Bonnet	1	\$ 1,980.00	\$ 1,980.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2007-088

DATE : 9-Jul-2020

POLICY NO. : FWD PNPV2020-00005998

VEHICLE REG. NO. : SML4183L

VEHICLE MAKE : HYUNDAI AD AVANTE 1.6 GLS (A) S

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
32	Front Bonnet Insulator Clip	10	\$ 3.00	\$ 30.00
33	Front Bonnet Rubber Seal	1	\$ 50.00	\$ 50.00
34	Duct Assy Extension - 28220E	1	\$ 220.00	\$ 220.00
Total Spare Parts				\$ 11,280.00
	<u>SPECIAL NETT</u>			
35	Front Tire LH (205 55 R16)	1	\$ 180.00	\$ 180.00
36	Coolant Fluid 4 Litre	1	\$ 30.00	\$ 30.00
Total Special Nett				\$ 210.00
	<u>LABOUR</u>			
37	Spray Painting Front Bonnet, Bumper, Fender LH & Doors LH	1	\$ 1,000.00	\$ 1,000.00
38	Repair, Replace and Refill Affected Accident Area Incl. Wheelhse	1	\$ 1,000.00	\$ 1,000.00
39	Remove and Replace Front Undercarriage	1	\$ 300.00	\$ 300.00
40	Wheels Computer Alignment / Wheel Balancing	1	\$ 80.00	\$ 80.00
41	Remove, Refit A/C Condenser, Radiator & Refill A/C Gas	1	\$ 100.00	\$ 100.00
42	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,510.00
Amount Before Excess				\$ 14,000.00
Add GST @ 7%				980.00
Total Amount Payable				\$ 14,980.00

Estimate prepared by: **Raymond Tan**

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.