

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 15 Jul 2020

Preliminary Advice

Vehicle No	: SLU6000H	Accident Date	: 09/07/2020
Make	: BMW 520D	Policy No.	: DMPCSN30807419000
Assignment Date	: 13/07/2020	Excess	: S\$0.00
Date of Inspection	: 15/07/2020	Est. Duration of Repair	: 3
Inspection At	: ELITE AUTOMOTIVE PTE LTD (HQ) 280 WOODLANDS INDUSTRIAL PARK E5, #01-17, HARVEST@WOODLANDS SINGAPORE 757322		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and n/s parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,803.10
Revised Amount	:S\$	8,103.84
Check Items (Estimated)	:S\$	1,358.96
Total	:S\$	9,462.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	158,000.00
COE / PARF Rebate	:S\$	72,414.00
Salvage Value	:S\$	
Margin for Repair	:S\$	85,586.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : REPAIR ON PART BY PART