

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM20007269/Bps3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	17/09/2021	
	ATTN:RICHARD			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLN 605P	Veh. Inspected	i	SLM 2946Y	
	Policy No.	VA1/GA340154	Coverage (\$)		0.00	
	Claim No.	S0M02QLQ	Excess (\$)		0.00	
	Assign From		Assign Date		14/07/2020	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 3	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6BN22A8H0143495	Colour		WHITE	
	Odometer	38950 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	POOR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	YOKOHAMA		5 mm	
	L/H Front Tyre	205/60 R16	YOKOHAMA		5 mm	
	R/H Rear Tyre	205/60 R16	YOKOHAMA		5 mm	
	L/H Rear Tyre	205/60 R16	YOKOHAMA		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	11/07/2020	Inspection Dat	e	14/07/2020	
	Survey held at	TEAM AUTOPRO PTE LTD				
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days					