



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD20004287/Gtf3e2-1

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 23-07-2020



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 7509L	Veh. Inspected	FBQ 291M
Policy No.	PNPV2020-00003170	Coverage (\$)	0.00
Claim No.	1202000013984	Excess (\$)	0.00
Assign From	JOSEY LOH	Assign Date	13/07/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA NMAX155	c.c	155
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3SG431000010587	Colour	WHITE
Odometer	34209	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/70-13	TIMSUN	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	130/70-13	TIMSUN	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/03/2020	Inspection Date	20/03/2020
Survey held at	BLK 5032 AMK IND PARK 2 #01-307		
Repairer	CCK CAR RENTAL		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------