

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

		FRE-REPAIR INS	LOII	ON KEI OKI		
LONPAC INSURANCE BHD				CS3/LPC20007278/	Gtf3e2	
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Date:	17-07-2020		
			Code:	LPC2		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	YN 7812H	Veh. I	nspected	SLW 2714Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/20/20/VC05/023458	Excess (\$)		0.00	
	Assign From	ONG LI LI	Assig	n Date	14/07/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA COROLLA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year o	of Reg.	2018	
	Chassis No.	MR053REH604576227	Colou	r	BROWN	
	Odometer	40077 KM	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modif	ication	SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	YOKOI	HAMA	6 mm	
	L/H Front Tyre	215/45 R17	YOKOI	HAMA	6 mm	
	R/H Rear Tyre	215/45 R17	YOKOI	HAMA	6 mm	
	L/H Rear Tyre	215/45 R17	YOKOI	HAMA	6 mm	
4.	l. Description of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	09/07/2020	Inspe	ct Date / Time	14/07/2020 ( 05:00 PM )	
	Survey held at	at LIM MOTOR PTE LTD  160 SIN MING DRIVE #05-20 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC20007278/Gtf3e2

Inspected By

**XING GUO QIANG** 

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.