

Date: 14.07.2020
Vehicle No: SLG9524S
Model: TOYOTA AQUA HYBRID 1.5S
Chassis: NHP106531199-2016
Reg.Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMK7171G
Date of Accident: 11.07.2020

ESTIMATE

Not withstanding
11 Sep @ 3900/-
5 days Resurvey After Painting

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH	1	my cm	\$1,374.30
2	FRONT BUMPER LAMP LH	1	cm	\$341.20
3	FRONT BUMPER	1	Bu	\$1,124.50
4	FRONT BUMPER SIDE BRACKET LH	1	Di	\$67.60
5	FRONT BUMPER CLIPS	8	\$5.20	\$41.60
6	FRONT FENDER LH	1	Bu	\$477.70
7	FRONT FENDER 'HYBRID' EMBLEM	1	Na	\$48.30
8	FRONT FENDER INNER LINER LH	1	Sm	\$216.90
9	FRONT FENDER INNER LINER CLIPS LH	10	\$5.50	\$55.00
10	FRONT WHEEL RIM LH	1	1805w L.I	\$397.80
11	FRONT WHEEL CAP LH	1	210	\$218.60
12	FRONT WHEEL RIM RH	1	1805w	\$397.80
13	FRONT WHEEL CAP RH	1	cm	\$218.60
14	FRONT LOWER ARM RH	1	Di	\$457.80
15	FRONT DOOR LH	1	REPAIR	
SUB TOTAL				\$5,437.70
LESS 25%				-\$1,359.43
PARTS TOTAL				\$4,078.28

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT TYRE TUBE VALVE LH	1	Na	\$12.00
2	FRONT TYRE TUBE VALVE RH	1	Na	\$12.00
S/N TOTAL				\$24.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$500.00 400/-

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT BOTH WHEEL RIM, FRONT BOTH TYRES, FRONT LOWER ARM RH & ETC.

\$180.00 150/-

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH & ETC.

\$700.00 600/-

Date: 14.07.2020
Vehicle No: SLG9524S
Model: TOYOTA AQUA HYBRID 1.5S
Chassis: NHP106531199-2016
Reg. Year: 2016

Third Party Insurer:
Third Party Veh No: SMK7171G
Date of Accident: 11.07.2020

D CHECK WIRING & ELECTRICAL SYSTEM.

201
\$80.00

D WHEEL ALIGNMENT & BALANCING.

\$60.00 ✓

LABOUR TOTAL \$1,520.00

ngAn

TOTAL \$5,622.28

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

