

Date: 14.07.2020
Vehicle No: SLG95245
Model: TOYOTA AQUA HYBRID 1.55
Chassis: NHP106531199-2016
Reg. Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SMK7171G
Date of Accident: 11.07.2020

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT \$S	AMOUNT \$S
1	FRONT HEADLAMP LH	1		\$1,374.30
2	FRONT BUMPER LAMP LH	1		CM \$341.20
3	FRONT BUMPER	1		BN \$1,124.50
4	FRONT BUMPER SIDE BRACKET LH	1		BN \$67.60
5	FRONT BUMPER CLIPS	8	\$5.20	BN \$41.60
6	FRONT FENDER LH	1		BN \$477.70
7	FRONT FENDER 'HYBRID' EMBLEM	1		BN \$48.30
8	FRONT FENDER INNER LINER LH	1		\$216.90
9	FRONT FENDER INNER LINER CLIPS LH	10	\$5.50	\$55.00
10	FRONT WHEEL RIM LH	1	L.I	R \$397.80
11	FRONT WHEEL CAP LH	1		BN \$218.60
12	FRONT WHEEL RIM RH	1		BN \$397.80
13	FRONT WHEEL CAP RH	1		CM \$218.60
14	FRONT LOWER ARM RH	1		\$457.80
15	FRONT DOOR LH	1		REPAIR
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey/re-insure/spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
SUB TOTAL				\$5,437.70
LESS 25%				-\$1,359.43
PARTS TOTAL				\$4,078.28

NO.	SPECIAL/NETT	QTY	UNIT \$S	AMOUNT \$S
1	FRONT TYRE TUBE VALVE LH	1		BN \$12.00
2	FRONT TYRE TUBE VALVE RH	1		BN \$12.00
S/N TOTAL				\$24.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. \$500.00 600/

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT BOTH WHEEL RIM, FRONT BOTH TYRES, FRONT LOWER ARM RH & ETC. \$180.00 7

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH & ETC. \$700.00 600/

Head Office
6 Kung Ching Road Singapore 159143
Tel: (65) 6472 1313 / Fax: (65) 6472 2112

Branch
8A Serangoon North Ave 5 Singapore 554500
Tel: (65) 6484 9919 / Fax: (65) 6481 1011

Branch
551 Upper Thomson Road Singapore 574415
Tel: (65) 6452 6868 / Fax: (65) 6452 9223



OPTIMA WERKZ SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201216485W
www.ow.sg E /optimawerkz

Date: 14.07.2020
Vehicle No: SLG95245
Model: TOYOTA AQUA HYBRID 1.5S
Chassis: NHP106531199-2016
Reg. Year: 2016

Third Party Insurer:
Third Party Veh No: SMK7171G
Date of Accident: 11.07.2020

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00

TO WHEEL ALIGNMENT & BALANCING.

\$60.00

LABOUR TOTAL \$1,520.00

TingAn TOTAL \$5,622.28

Head Office
6 Rong Chang Road Singapore 19143
Tel: (+65) 6472 1313 / Fax: (+65) 6472 2112

Branch
84 Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 / Fax: (+65) 6481 1011

Branch
551 Upper Thomson Road Singapore 574615
Tel: (+65) 6452 6868 / Fax: (+65) 6452 9223

