



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20007309/R1vf3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 20-08-2020



Code : UOI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SGZ 8999X
Policy No.	DHOM120023791601	Coverage (\$)	0.00
Claim No.	M12D13552007	Excess (\$)	750.00
Assign From	JOSEPHINE WONG	Assign Date	15/07/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X5 M50D LED M SP	c.c	2993
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WBAKS820300G66431	Colour	BLACK
Odometer	48109	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	315/35 R20	PIRELLI	6 mm
L/H Front Tyre	315/35 R20	PIRELLI	6 mm
R/H Rear Tyre	315/35 R20	PIRELLI	6 mm
L/H Rear Tyre	315/35 R20	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/07/2020	Inspection Date	15/07/2020
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE MARKET VALUE IS S\$173,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------