

96756563 - Tommy

VINTAGE INVESTMENT PTE
LTD

Date : 08/07/20

Ref : ST008/20

Page : 1 of 2

Attn : Officer in charge

Parts for the Porsche Cayenne 2020 Model

Chassis : WP1ZZZ9YZLDA04151

	Des	Qty	U/P	Amount
1. Front headlamp ✓ CDA		2	\$4,300.00	\$8,600.00 7239
2. Radiator 25110 ✓ BR		1	\$1,500.00	\$1,500.00 1281
3. Condenser (6421) ✓ CUT		1	\$2,600.00	\$2,600.00 1857.9
4. Front Bumper (G2X) ✓ CUT		1	\$2,870.00	\$2,870.00 2235.9
5. Front Bonnet (00 GRV) ✓ BT		1	\$4,800.00	\$4,800.00 3686.4
6. Center Grille (POK1) ✓ BR		1	\$460.00	\$460.00 380
7. Front air flap center low (451hok1) ✓ CUT		1	\$675.00	\$675.00 550
8. Bumper insulator (665) ✓ BR		1	\$160.00	\$160.00 136
9. Front upper carrier (5015c) ✓ BT		1	\$1,245.00	\$1,245.00 1058
10. Front air guide center lower (710 ok1) ✓ BR		1	\$264.00	\$264.00 211
11. Air guide centre upper (673) ✓ BR		1	\$450.00	\$450.00 360
12. Cross member upper (241b) ✓ BR		1	\$237.00	\$237.00 189.6
13. Front air duct (251b) ✓ CDA		1	\$170.00	\$170.00 136
14. Air guide L & R side (700/699cok1) ✓ CDA		2	\$200.00	\$400.00 320
15. Front air shutter (519fok1) ✓ BR		1	\$1,000.00	\$1,000.00 800
16. F/bumper inner moulding (179041A/B) ✓ BR		3	\$180.00	\$540.00 405
17. Center lower grille (684 Ok1) ✓ BR		1	\$345.00	\$345.00 276
18. Front bumper crash sensor (651F) ✓ DM		1	\$354.00	\$354.00 265.5
19. Front end support (711c) ✓ BR		1	\$90.00	\$90.00 72
20. Front radiator support (594L) ✓ BR		1	\$1,217.00	\$1,217.00 810.1
21. Front foam part (7550F) ✓ CDA		1	\$85.00	\$85.00 68
22. Front Reinforcement Bar (109B) ✓ BT		1	\$1,500.00	\$1,500.00 1200
23. Front Bonnet Hinger (301/302D) ✓ BT		2	\$380.00	\$760.00 608
24. Wire harness ✓ DM		1	\$800.00	\$800.00 640
25. Front camera with 360 view control unit ✓ NW		1	\$4,800.00	\$4,800.00 800
26. Actuating lever (661D) ✓ SBT		1	\$52.00	\$52.00 39
27. House Lock (529E) ✓ SBT		1	\$200.00	\$200.00 160
28. Vent line (125) ✓ BT		1	\$150.00	\$150.00 120
29. Front lower spoiler (061ok1) ✓ CRA		1	\$1,860.00	\$1,860.00 1488

SINGTRADE INVESTMENT PTE
LTD

Date : 08/07/20

Ref : ST008/20

Page : 2 of 2

30. Cover centre black mat (504 cok1) ✓	1	\$590.00
31. Cover LH black mat (441 cok1) ✓	1	\$450.00
32. Cover RH black mat (442 cok1) ✓	1	\$450.00
33. Licence plate holder (287 0k1) ✓	1	\$240.00
34. Front bonnet " Porsche emble " ✓	1	\$639.00

\$590.00	472
\$450.00	360
\$450.00	360
\$240.00	40
\$639.00	280

Sundries (clip / nuts / rivetted cap)

\$500.00

Top aircon gas

\$150.00

Top up radiator coolant

\$180.00

Labour charge (for 10 days work)

\$5,000.00

Spray paint (bonnet/bumper/
bonnet hinger)

\$3,000.00

Claim for loses

\$15,000.00

160 Sin Ming Drive , Sin Ming Autocity
#08-02

Singapore 575722

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

50
50
50

1500

900

2550

28904.7
10% = 26013.96

28563.96

10 Days