

**ESTIMATE** 

UEN: 201820703D

13 KAKI BUKIT ROAD 4

BARTLEY BIZ CENTRE #01-04 SINGAPORE 417807 Office; +65 69763531 Hp: +65 9222 9111 Email: operations@convergence.com.sg

OWNER NAME: CHANG WENG LUM

OWNER NRIC: SXXXX263A OWNER CONTACT: '+65 9367 9667 DATE VEHICLE NO: 15 July 2020 SCG623E

VEHICLE MAKE:

BMW

VEHICLE MODEL: CHASSIS NO.: 116D-1.5 D 5DR HATCH LED (A)

WBA1V72000V724394

DESCRIPTION	QUANTITY	AMOUNT	TOTAL
PARTS LIST			
1) Tailgate ✓ DD	1.00	\$1,150.00	\$1,150.00
2) Rear Bumper   DEF	1.00	\$880.00	\$880.00
		Total Parts Cost	\$2,030.00
GST Paid to Suppiler	-	-	\$142.10
		Total Parts Cost	\$2,172.10
Labour Charges			
Labour		\$500.00	400√ <sub>\$500.00</sub>
Spray Paint Panel		\$600.00	400 ✓ \$600.00
Sundrise Material (5% of spray paint)			NEC \$30.00

**TOTAL SUM** 

\$3,302.10

PAGE 1

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK) 16/07/20, 2.30pm Without Prejudice 4 repair days Lumpsum Resurvey After Spray