

A member of COMFORIDELGRO

GST REG. NO. M2-8921817-3

## TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Staddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

 Workshops
 59 Loyang Drive Singapore 508969
 24 Senoko Loop Singapore 758156

 383 Sin Ming Drive Singapore 575717
 7 Sungel Kadul Way Singapore 728791

 59 Paudan Road Singapore 608649
 50 Yishun Industrial Park A Singapore 768732

NO/DATE 91515315 20.07.2020

ODOMETER READING

COMPANY REG. NO.: 199506048W

JOB NO. 305410694

Page: 1

8010056

QBE INSURANCE (INT'L)LTD

1 RAFFLES QUAY SOUTH TOWER #29-10 SINGAPORE 048583

CONTACT NO: 62246633

DATE OF REG 03.12.2015

VEHCLE NO SHC8775J

MAKE HYUNDAI

MODEL I - 40

> CHASSIS CODE KMHLB41UMGU080757 JOB TYPE

Description: 3P 13.07.2020

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt 7.000 % 1,600.00 112.00

1,712.00 Total Invoice amount

KATHERINETAN 20.07.2020 11:26:28 CLSO/57/57


Issued by : KATHERINETAN 20 Repair Type : CLSO/57/57 Payment Type/Term : /Credit 30 days

omfortDelGro Engineering Pte Ltd member of COMFORTDELGRO

ead Office: 35 Braddell Road ingapore 579701

indly note that no receipt shall be issued unless requested.

**SUSTOMER'S COPY** 



Our Ref: CT20070165

Date: 20 July 2020



## TO WHOM IT MAY CONCERN

Dear Sir/Madam

**ACCIDENT ON** 

13/07/2020 @ 15:45 hrs

ALONG

ALONG PUNGGOL CENTRAL RD TOWARDS

**PUNGGOL RD** 

INVOLVING

YN7127C

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC8775J (the "Taxi"). The Taxi was hired to TEO KOK HOON IC NO SXXXX122Z a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$110.67 per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	1000	00000	MILEAGE	HOURS OPERATED (TIME	DATE	NAME OF DRIVER	MILEAGE
DATE	NAME OF DRIVER	MILEAGE READING	TRAVELLED (KM)	FROM TO	1 100		
12.2.20	STATES ! O	281278	273	04.351.526			
18 18 1 18 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1	S. FANDS	862298	113-9	1600 22018			
18.4.20	NA CAN	863503	1,500	5.40mm H30mm			
ちょうのプロイング	7 - Nooden -	7032	1100	UPCEC (1)			
100.000	Corporati		OW	1000 -			
できる そいへい	18 8 00 CA	アカーチ	-E0	3, 1:30			
	.686 22	P. 0	916	N. C. P			
278 W. T.S.	7 1 0000	\$ 10 to 10 t	. Let	0.7.00			
Ste oak	7 78 33 34	70. Y	Mes.	0KC [5:0)			
\$ 00 12 Ja	1 1200	* 7 4 70	色	1.4.40		(S)	
T+5 8/1	L. SASE	7 3 9	To	38.1.1.18			

## **Enquire Vehicle Insurance Details**

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
YN7127C	13 Jul 2020 / 15:45:00	Successful	Q01	QBE INSURANCE (SINGAPORE) PTE LTD
YN7127C	13 Jul 2020 / 15:45:00	Successful	C05	LIBERTY INS P L

## Disclaimer message:

Your search is displaying 2 records as there is an overlap in the period covered by the insurance policies. You may wish to contact the insurance companies for more information.

Previous OK

SUC 8778]

13/07/2020 @ 1655hrs

Specific to Andrew Like

(QBE) 6477 (243. Ke confirmed

that relieb insured by QBE.

1705hr - Spoke to Me Hasting (Liberty)

Veh not insured with fram.

Lorst appelate was theyout 19