Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007368/GGS3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant Vehicle No: SLN3063H Insured Vehicle No: SH8781J

Date of Loss: 12/07/2020 Nature of Claim: TP Claim No: MCT20070155

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN3063H

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UGB1599

Reg. Date: 28/04/2017 (Man. Year: 2017) Chassis No: MMBSTA13AHH006028

Colour: Red Odometer: 254716 km

Engine Capacity: 1193 cc Market Value/New Car

Price: N/F

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	976.00	976.00	0.00	0.00
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	175.00	150.00	25.00	14.29
Paintwork Labour	451.20	451.20	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,613.20	1,588.20	25.00	1.55
Approved Total (Overridden) (S\$)		1,577.20		
(S\$)	1,613.20	1,577.20	36.00	2.23
+ GST 7.00/7.00% (S\$)	112.92	110.40	2.52	2.23
Nett Amount (S\$)	1,726.12	1,687.60	38.52	2.23
+ Car Rental (6.0 x S\$100.00/day + 7	'.00% GST) (S\$)	642.00		
+ Doc/S	Search Fee (S\$)	7.49		
Ne	ett Liability (S\$)	2,337.09		

INSPECTION

Date of Assignment: 16/07/2020 Present Location: Mova Automotive Pte Ltd (Bukit

Merah)

Date Inspected: 04/08/2020 Inspected At: Mova Automotive Pte Ltd (Bukit

Merah)

Blk 1008, #01-04/06/08/94, Bukit

Merah Lane 3 Singapore 159722 Adjuster Report Page 2 of 4

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference Part Source: (Last Synchronised: 12 Nov 2020) MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database) Parts: N/A Labour: Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SLN3063H) Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*R/R LAMP	Scratched	276.00 FL	*276.00 FL
2	1	NA	*R/R OUT BUMPER BRKT	Deformed	26.00 FL	*26.00 FL
3	1	NA	*REAR BUMPER	Deformed	708.00 FL	*708.00 FL
4	1	NA	*REAR BUMPER MNTG KIT	Necessary	30.00 FL	*30.00 FL
5	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 FL	*- FL
6	1	NA	*AUDATEX FEE SN	Necessary	40.00 FS	*40.00 FS
F=Fra	ınchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	1,080.00	1,080.00
	- List Item Discount on L Items 10.00/10.00% (S\$)			104.00	104.00	
				Total Parts (S\$)	976.00	976.00
			Report was unsubm	itted during this print-out.		

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=... 30/12/2020

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellar	neous Items			
1	1	OD/TP Case (Insurer)	_	11.00	11.00
			Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Pair	ntwork Labour			
1	Total Paint Labour	New	325.00	325.00
2	Total Paint Materials	New	126.20	126.20
Lab	our Items			
3	Total Panel/Mechanical Labour	New	175.00	150.00
		Gross Labour Cost (S\$)	626.20	601.20

Report was unsubmitted during this print-out.

< END OF ESTIMATES >