

MOVA Automotive Pte Ltd
Blk 1008, Bukit Merah Lane 3,
#01-04/06/08. Singapore 159722

Insurer Reference:
Repairer Reference: CK138578
Date calculated: 15/07/2020 6:03 PM

Full Report
Registration: SLN3063H
Printed: 15/07/2020 6:05 PM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	TP / India International Insurance
Printed by:	Jacelyn Ooi	Currency:	SGD
Claim Reference:	9686-9275	Date of Incident:	12/07/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle		
Manufacturer:	MITSUBISHI	
Model:	ATTRAGE (A13A)	
Sub Model:	BASE MODEL	
Model Sheet Number:	32 AT 01	
Registration:	SLN3063H	
VIN number:	MMBSTA13AHH006028	
Odometer:		
Model Specs		
FROM 03/2017	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



		Time Base 10 WU/h	Price = 50.00 SGD/h	
Description			WU	Price SGD
R	PREPARATION TIME		2.0	10.00
J	REAR BUMPER (REMOVED) RENEW		5.0	25.00
INCLUDES: REQUIRED ATTACHED PARTS				
REMOVE AND REFIT				
00	R + R RIGHT TAILLAMP		3.0	15.00
	REAR PANEL CPL REPAIR		10.0*	50.00
	R/R OUT QTR PANEL REPAIR		15.0*	75.00
Labour Cost				
Panel / Mechanical Labour		Hrs	WU	
		3.50	35.0	175.00
Total of Labour			150	175.00

Paint

Paint Work

Code

		SYSTEM AZT	Time Basis 10 WU/h	
Description - TWO COAT METALLIC			WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		12.0	
	REAR PANEL CPL REPAIR PAINTING <50%		12.0	
	R/R OUT QTR PANEL REPAIR PAINTING <50%		11.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	59.53
2711	REAR PANEL CPL REPAIR PAINTING <50%	14.86
3482	R/R OUT QTR PANEL REPAIR PAINTING <50%	14.21

Labour Cost - Paint

Factor	50.00 SGD/h	Hrs	WU	Price SGD
Time Paint			35.0	
Preparation Main Work Metal		2.50	25.0	125.00
Preparation Comp. Work Plastic		0.50	5.0	25.00
Total	10 WU/h	6.50	65.0	325.00 ✓

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	59.53
Repair Painting	29.07
Material-constant Metal Preparation	28.60
Material-constant Plastic	9.00
Total	126.20 ✓

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01
				Price SGD

Description	Part Number	Part Source	Price SGD
R/R LAMP ✓ SCR	8330A852	Original	276.00
R/R OUT BUMPER BRKT ✓	6410C434 DE	Original	26.00
REAR BUMPER ✓ DE	6410C750	Original	708.00
REAR BUMPER MNTG KIT USE SINGLE PARTS	Original ✓	NEC	30.00

EM Parts	Savings	0.00
Non-OEM Parts	Subtotal	1,040.00
∴ Used parts	Subtotal Discount(+10.00%)	-104.00
	Total	936.00

Extras

Code	Description	Price SGD
1000	AUDATEX FEE SN	40.00*
	Total Extras	40.00

Final Calculation

	SGD	SGD
Parts		
Total Discount(+10.00%)	1,040.00	
Total Parts	-104.00	936.00
Labour Time Base 10 WU/h		
Total 35.0 WU X 50.00 SGD/h	175.00	
Total of Labour		175.00
Total Of Extras		40.00
Paint Work Time Base 10 WU/h		
Labour Cost 65.0 WU X 50.00 SGD/h	325.00	
Material Cost	126.20	
Total Paint Including Material		451.20
Repair Cost Excludes GST	1577.2	1,602.20
GST (+7.0%)		112.15
Repair Cost Included GST		1,714.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

part by part.

before part photos.

3 Days.

Guo Qiang - 8288 0282

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Guo Qiang @ LKK Auto. com
04/8/2020.