

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

Not Authorized
C11mg @ 1850/-
Pursuing After Claim
4 days

REPAIR ESTIMATE FOR SGU4942L

No.	Qty	List Items			
1	1	Front bumper	my \$M	447.25	—
2	1	Front bumper RH side retainer	\$ mi	65.40	—
3	1	RH headlamp	\$ M	383.50	—
4	1	Front RH fender	\$ R	530.10	X
5	1	Front RH fender under shield	\$ R	158.40	X
6	1 set	Front fender under shield clips	\$ R	30.00	X
7	1	Front RH shock absorber	\$ R	202.40	X
8	1	Front RH lower arm	\$ R	256.30	X
9	1	Front RH knuckle arm	\$ R	421.60	X
10	1	Front RH wheel hub & bearing	\$ R	146.00	X
11	1	Front RH drive shaft	\$ R	958.00	X
			\$	3,598.95	
		Less 25%	\$	899.74	
		Total :	\$	2,699.21	
<u>Special Nett Items</u>					
12	1	Front bumper lower skirting	\$ R	1,000.00	X
13	1	Front RH tyre	\$ R	220.00	X
14	1	Front RH sports rims	\$ R	500.00	2800
		Total :	\$	1,720.00	
<u>Labour</u>					
1		Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$	600.00	400
2		To putty and spray Spray Paintings charges.	\$	600.00	400
3		To check wirings and lightings.	\$	40.00	20
4		To remove, refit front under carriages.	\$	250.00	100
5		To conduct computerise wheel alignment test.	\$	80.00	60
6		To supply and apply anti rust treatment	\$ R	60.00	X
		Total :	\$	1,630.00	
Total Parts and Labour :			\$	6,049.21	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: