

Section A - Accident Details

Registration Number	SHF130G
Case Reference Number	TAX/07/20/2025
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	LEAN CHEONG SOON
Type of Accident	Head to Rear
Accident Date and Time	14/7/2020 6:30 PM
Accident Reported Date and Time	15/7/2020 9:48 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24107545
Special Instruction to ARC, if any	TP / REAR LEFT PORTION
Prepared Date and Time	15/7/2020 12:47 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,264.00	\$600.00
Total Spray Cost	\$2,754.00	\$600.00
Total Spare Part Cost	\$11,110.71	\$3,533.00
Total Other Cost	\$1,975.00	(\$682.89)
TOTAL COST	\$17,103.71	\$4,050.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	18/07/2020 9:29 AM	20/07/2020 10:46 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = +1 day.	L/S, after paint photo

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2008-0031	Invoice Number	
Quotation Date	05.08.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	\$1,014.00	\$400.00 /
TO REPAIR REAR END PANEL	\$250.00	\$200.00 /
Total Labour	\$1,264.00	\$600.00 / <i>Supp</i>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$100.00 /
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00 /
TO RESPRAY REAR SPOILER	\$180.00	\$100.00 /
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$0.00
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00 /
Total Spray Painting & Panel Beating	\$2,754.00	\$600.00 / <i>Supp</i>

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$475.00	\$125.00 /
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$100.00 /
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$988.00)
Total Other Costs	\$1,975.00	(\$683.00)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace ✓
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace ✓
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace ✓
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace ✓
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace ✓
		5219147030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace ✓
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check ✗
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given ✗
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace ✓
		5257647040	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace ✓
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given ✗
		9018906029	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given ✗
		5256647900	FILLER, RR BUMPER, LH	1.00	\$119.90	25.00	\$89.93	Replace	Replace ✓
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace ✓
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace ✓
		8159147010	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$486.80	10.00	\$438.12	Replace	Replace ✓
		5839947030	COVER, REAR FLOOR UNDER, LH	1.00	\$234.30	25.00	\$175.73	Replace	Replace ✓
		6625947010	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given ✗
		5259247040	SEAL, RR BUMPER, LH	1.00	\$85.20	25.00	\$63.90	Replace	Replace ✓
		6700547440	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given ✗
		7680147110A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	0.00	\$891.20	0.00	\$0.00	Replace	Not Given ✗
		6810547291	TAIL GATE GLASS SUB-ASSY, BACK DOOR	0.00	\$1,569.70	0.00	\$0.00	Replace	Not Given ✗
		5611750140	TAIL GATE DAM, BACK DOOR GLASS UPPER	0.00	\$27.90	0.00	\$0.00	Replace	Not Given ✗
			SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given ✗
		6480147031	TAIL GATE LOWER GLASS SUB-ASSY, BACK	1.00	\$725.90	25.00	\$544.43	Replace	Replace ✓
		5611750140	TAIL GATE DAM, BACK DOOR GLASS UPPER	1.00	\$27.90	25.00	\$20.93	Replace	Replace ✓
		7557447040	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$29.90	25.00	\$22.43	Replace	Replace ✓
		7557347110	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$29.90	25.00	\$22.43	Replace	Replace ✓
		7557547051	TAIL GATE MOULDING LOWER GLASS, BACK	1.00	\$19.70	25.00	\$14.77	Replace	Replace ✓
			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace ✓
		7540348010	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace ✓
		7544147090	NAME PLATE (HYBRID), LUGGAGE	1.00	\$52.30	25.00	\$39.23	Replace	Replace ✓
		7544247130	NAME PLATE (PRIUS), LUGGAGE	1.00	\$52.30	25.00	\$39.23	Replace	Replace ✓
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
			STICKER DECAL 6555888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
		7608547916	SPOILER SUB-ASSY, REAR	1.00	\$1,322.10	100.00	\$0.00	Replace	Repair ✓
		8100647030	LAMP SET, STOP CENTER	0.00	\$186.50	0.00	\$0.00	Replace	Not Given ✗
		5830747090	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Not Given ✗
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given ✗
		5831647010	EXTENSION, REAR FLOOR SIDE PANEL, LH	0.00	\$76.20	0.00	\$0.00	Replace	Not Given ✗
		6499747060	BOX, DECK FLOOR, LH	0.00	\$303.40	0.00	\$0.00	Replace	Not Given ✗

	64740471 90C2	PANEL ASSY, DECK TRIM SIDE, LH	0.00	\$344.70	0.00	\$0.00	Replace	Not Given	X
	81561471 51	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$438.10	10.00	\$394.29	Replace	Replace	
	81498470 20	COVER, REAR COMBINATION LAMP, LH	1.00	\$54.00	25.00	\$40.50	Replace	Replace	
	61622470 60	TROUGH, BACK DOOR, LH	0.00	\$99.80	0.00	\$0.00	Replace	Not Given	X
	61602471 60	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given	X
	62940470 10	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	X
	65638470 60	LINER, REAR FENDER, LH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X
Total				\$13,538.94		\$2,997.14			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		81455420 60	LED, RR FOG LAMP	1.00	\$94.80	10.00	\$85.33	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		67881470 50	TAIL GATE WEATHERSTRIP, BACK	1.00	\$360.70	25.00	\$270.53	Replace	Replace
Total					635.50		535.86		

CR4
Short
CR4

3533.00 /
 + 600.00 /
 + 905.00 /

 5038.00 /
 - 202 /

 4030.40 /
 2/3 \$4050 /
 4 days