

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 21 Aug 2020

Preliminary Advice

Insured Vehicle No	: SLP1417Z		
TP Vehicle No	: SMH953D	Accident Date	: 16/07/2020
Make	: HONDA VEZEL	Assignment Date	: 17/07/2020
Date of Inspection	: 17/07/2020	Est. Duration of Repair	: 7 days
Inspection At	: Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,100.24
Revised Amount	:S\$	8,167.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,167.60
Lump Sum Repair	:S\$	6,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.