

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

17, July 2020

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way AIG Building
#07-16 S 079120

Not Not hatched
11 Sep @ 4:00pm
Recovery After Paint
Delays

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SMD2213P

Accident involving vehicle no: SKD1821P/SMD2213P

DOA: 16/07/2020 AT Along Upp Bukit Timah Rd Nr Junction of old Jurong Rd

Dear officer incharge

Estimate cost of repair for vehicle no: SKD1821P

To supply—

Description	Qty	Amount
Rear bumper	1 <i>BT/CMA</i>	482.00 ✓
Rear bumper retainer @72.70	2 <i>Dis</i>	145.40 ✓
Rear bumper sponge	1 <i>CMA</i>	117.50 ✓
Rear bumper clip/screw	<i>Re</i>	38.00 ✓
Rear bumper reflector @37.20	2 <i>Re</i>	74.40 X
Tailgate	1 <i>Re</i>	754.30 ✓
Tailgate lock	1 <i>Re</i>	96.50 ✓
Tailgate reflector @116.60	2 <i>Re</i>	233.20 X
Tailgate chrome handle	1 <i>CMA</i>	332.98 ✓
Tailgate 1.6 emblem	1 <i>Re</i>	32.10 ✓
Tailgate VVTI emblem	1 <i>Re</i>	38.40 ✓
Tailgate altis emblem	1 <i>Re</i>	42.35 ✓
Tailgate-corolla emblem	1 <i>Re</i>	45.00 ✓
Boot weather strip	1 <i>nd/Re</i>	175.35 <i>5.08km 87.67km</i>
Taillamp @281.90	2 <i>mg CMA</i>	563.80 ✓
End panel	1 <i>Re</i>	581.20 ✓
Spare tyre panel	1 <i>BT/Re</i>	702.90 ?
Spare tyre board	1 <i>CMA</i>	227.20 ✓
Rear bumper bracket @82.80	2 <i>BT</i>	165.60 ✓
End panel top garnish	1 <i>CMA</i>	202.70 ✓
Fender, rear Lh	1 <i>Re</i>	602.40 X
Parts		5,653.28
Parts less 25%		1,413.32
		4,239.96

Reverse sensor

Shen 220.00 200.00

To remove/reinstall rear windscreen glass

nn 160.00 X

To remove inner garnish, rear seater cushion, rear speaker board enable repair

Job carrypout, reinstall job done

150.00 80.00

To remove damaged parts n attachments

Cut n weld damaged fender

Straighten rear chassis where necessary

Repair/reshape all dented/damaged areas

1,650.00 800.00 1100.00

To replace/align all parts into position

1,600.00 900.00

To spray paint

8,019.96

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: