



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : INDIA INTERNATIONAL INSURANCE PTE  
 64 CECIL STREET  
 #04-00 & #05-00 IOB BUILDING  
 SINGAPORE 049711

**Registration No** : SLA8539M

**Chassis No** : MRHRU1830FP000834

**Model** : HRV LX-SIN CVT YM 2015

**Owner's Name** : KHO SOON IMM

**Ins Policy No.** :

**Date of Accident** : 17/7/2020

**Document No.** : SQT20002185 Page 3

**Date** : 18. Jul 2020

**Customer No.** : WZ1007

**Svc Advisor** : IVAN TEO BOON KIAT

**Engine No** : L15Z71001525

**Date | Time** : 18. Jul 2020 11:00:30 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	560.00	480	560.00	39.20	599.20
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	560.00	480	560.00	39.20	599.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	325	650.00	45.50	695.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR (N)	1	350.00		350.00	24.50	374.50
BKRP02B	CUT & RENEW RR FLOOR PANEL, END PANEL & DAMAGE PART @650	1	6500.00	5200	3500.00	455.00	6955.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P) @520	1	4160.00	2600	4160.00	291.20	4451.20
BOBC	BODY UNDERSIDE COATING (N)	1	450.00	300	450.00	31.50	481.50
<b>Sum Labor</b>					<b>15540.00</b>	<b>1,087.80</b>	<b>16,627.80</b>

Survey By RASUL - Hp 90010068

Date & Time 23/07/2020 @ 1130 12 days

Excess \_\_\_\_\_

Status \_\_\_\_\_

Signature [Signature] Resy before paint

Total Amount 19,960.41 1,397.25 21,357.66

Total (Inclusive of GST) 21,357.66

20,400.44#

\* Supplementary  
GPIs refer to Service  
Pre-Invoice.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 18/7/2020 12:02:42 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.