## Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-17 International Plaza Singapore 079903.

Tel: 90036715 Fax: 62256130 Email: soonbee\_vehicle@yahoo.com.sg

GST Registration No: 53076555A

Our Ref No.: SB-18420

Date: 17-Jul-20

AMK Workshop.

Foreman: Li Ming FAX: 64562752

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

## **QUOTATION FOR ACCIDENT REPAIR ON BUS NO:**

**SBS6008R** 

We are pleased to offer our best proposal to provide our services of labour for repair of above mentioned vehicle at SBS Transit, Ang Mo Kio Workshop.

14)	Vehicle No :	SBS6008R
1)	Model :	ISD ISD
	IVIOGO: .	
2)	Total Cost :	- Material & Parts Cost :
\ .		Labour Cost : \$ 640.00
		- Labour Cost
		GST (7%) : \$ 44.80 Total : \$ 684.80
		I Otal: \$ 004.00
		work Scopes
		Renair o/s No. 4 & 5 body panel
	1	Repair o/s/r battery access door 200t My hot / before payury product
		Touch up putty on accident area
		$\frac{1}{2}$
		Total: \$ 684.80  Work Scopes  Repair o/s No. 4 & 5 body panel Repair o/s/r battery access door Touch up putty on accident area  Quality of the fore patting photos  Auo Qiang - 8 188 0282  Quality on accident area  Auo Qiang B IKIC auto. Com
		auo Qiang - 8 colors
	1	Ding @ IKIC auto. com
		Quo (xian) C
	1	Ses and Signal Strikly
		Supply workers for 2 day work
		TERM OF PAYMENT: 30 DAYS UPON DELIVERY OF VEHICLES
		Vehicle Electric and wiring system not included
		(B) Materials and Parts:
		- Supply by SBS Transit
		ON Markarian I/Engine Effect
		C) Mechanical/Engine Effect - NA
		- 140

Note: Quotation valid for 1 Month only

This is a computer-generated document. No signature will be required.