



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

Not Authorised

*11 Sep @ 6900h
Pulau Ater Park*

Estimate: ES007006

CHOON HOCK TERENCE
RONG LAKE LINK #02-35
APORE 648131

ion : THE OWNER

act : 81181881

Date : 20/07/2020
Vehicle Num. : SBB541X
Make/Model : TOYOTA HARRIER PREMIUM 2.0 CVT
Chassis/Eng# : ZSU600072718/3ZRB731637
Accident Date : 18/07/2020
Claim No. :
Reference :
Policy No. :

Quantity	Particular	Unit Price	Amount S\$
----------	------------	------------	------------

LIST ITEMS :

1	FRONT FENDER R/H	764.50	212
1	FRONT FENDER INNER SHIELD REAR R/H		
1	FRONT BUMPER		
1	FRONT BUMPER SIDE RETAINER R/H		
6	FRONT BUMPER CLIP		
1	HEADLAMP R/H		
1	FRONT DOOR R/H	1266.30	
1	FRONT DOOR LOWER CHROME MOULDING R/H		
1	FRONT DOOR LOWER HINGE R/H		
1	FRONT DOOR UPPER HINGE R/H		
1	FRONT DOOR CHECK R/H		
1	FRONT DOOR RUBBER SEAL R/H		
1	FRONT DOOR SUN VISOR R/H		
2	FRONT DOOR FRAME STICKER R/H		
1	FRONT DOOR GLASS CHANNEL R/H		
1	FRONT DOOR INNER LOWER RUBBER R/H		
1	FRONT DOOR SPEAKER R/H	381	
1	REAR DOOR R/H		
1	SIDE SKIRTING GARNISH R/H		
1	REAR BUMPER		
1	REAR BUMPER SIDE RETAINER R/H		
1	RUNNING BOARD PANEL R/H		
1	FRONT SPORT RIM R/H		
1	FRONT SHOCK ABSORBER R/H		
1	FRONT WHEEL BEARING R/H	402.10	Wheel Alignment
1	FRONT LOWER ARM R/H	411.20	
1	FRONT KNUCKLE ARM R/H		
1	FRONT DOOR PILLAR OUTER R/H		
1	FRONT DOOR MIRROR COVER R/H		

R	1,112.00	✓
my car	409.00	✓
Sm	861.30	✓
	92.33	X
6.50	39.00	✓
Sm	3,687.00	X
R	1,560.00	✓
car	221.20	✓
dit	87.00	✓
dit	87.00	X
dit	138.50	✓
car	196.78	✓
car	118.00	✓
79.20	158.40	X
Sm	262.40	X
car	89.20	✓
car	552.00	✓
R	1,319.00	X
Sm	585.20	✓
R	1,351.20	X
Sm	92.33	X
R	862.00	X
car	769.00	✓
R	255.20	✓
car	642.10	✓
dit	493.20	✓
R	541.60	✓
R	852.00	X
Sm	179.00	X

CONTINUE / ...

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

N CHOON HOCK TERENCE
JURONG LAKE LINK #02-35
SINGAPORE 648131

Attention : THE OWNER
Contact : 81181881

Estimate #: ES007006

Date : 20/07/2020
Vehicle Num. : SBB541X
Make/Model : TOYOTA HARRIER PREMIUM 2.0 CVT
Chassis/Eng# : ZSU600072718/3ZRB731637
Accident Date : 18/07/2020
Claim No. :
Reference :
Policy No. :

Quantity	Particular	Unit Price	Amount S\$
----------	------------	------------	------------

1	REAR SPORT RIM R/H		
1	FRONT WIPER GARNISH R/H		
1	FRONT FENDER TOP RUBBER R/H		
1	FRONT DOOR INNER BOARD R/H		

Sum 769.00 X
Sum 69.00 X
Sum 152.00 X
Sum 965.00 2

List Total S\$:
25.00% Discount S\$:

19,567.94
4,891.99
14,675.95

LABOUR :
TO TRANSFER R/H FRONT DOOR COMPONENT TO NEW DOOR
RUST PROOFING TREATMENT
REMOVE & REINSTALL FRONT SUSPENSION R/H
COMPUTER WHEEL ALIGNMENT
SPRAY PAINT DAMAGED AREA AFFECTED
CHANGE HEAD LAMP & DO LIGHT BEAM LEVEL ADAPTATION
TO CUT OFF R/H RUNNING BOARD PANEL, R/H FRONT PILLAR
LOWER, KNOCK AND STRAIGHTEN FRONT CHASSIS FRAME AND
RE-ALIGN BODY

bol 180.00
bol 100.00
bol 250.00
bol 120.00
1100 1,200.00
300 90.00

Labour Total S\$:

700 1,100.00
3,040.00

Dollars : Seventeen Thousand Seven Hundred Fifteen & Cents Ninety-Five Only

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total S\$: 17,715.95

Acknowledged by Repairer
Signature:
Date:

COMPLETE VMS PTE LTD

This is only an estimate based on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

TAN CHOON HOCK TERENCE
10 JURONG LAKE LINK #02-35
SINGAPORE 648131

Attention : THE OWNER

Contact : 81181881

Supplementary Estimate : ES007007

Date : 22/07/2020
Vehicle Num. : SBB541X
Make/Model : TOYOTA HARRIER PREMIUM 2.0 CVT
Chassis/Eng# : ZSU600072718/3ZRB731637
Accident Date : 18/07/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS : FRONT FENDER REAR INNER GARNISH		
		List TotalS\$:		125.20
		25.00% Discount S\$:		31.30
		1 R/H Left door inner soundproof		93.90
		1506		

SingDollars : Ninety-Three & Cents Ninety Only

Total S\$: 93.90

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun