

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXXX897F
KOH JIEXI, NICHOLAS
BLK 608B TAMPINES NORTH DRIVE 1
11-320
SINGAPORE 522608
TEL : FAX :
PH : 91006768
ATTN :

ESTIMATE BILL

Number : EB00005498
Date : 21/07/2020
Case No : AD00011193
Vehicle No : SJR6862B
Chassis : MR053HY9305119509
Year of Mfr : 2009
Policy No :
Model : TOYOTA VIOS E
AUTO

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	END PANEL	1.0	551.70	25	413.78
2	END PANEL TOP GARNISH	1.0	200.76	25	150.57
3	REAR BUMPER	1.0	431.90	25	323.93
4	REAR BUMPER RETAINER LH	1.0	87.90	25	65.93
5	REAR BUMPER RETAINER RH	1.0	87.90	25	65.93
6	REAR BUMPER BRACKET RH	1.0	77.30	25	57.98
7	REAR BUMPER BRACKET LH	1.0	77.30	25	57.98
8	BOOTLID LOCK	1.0	102.50	25	76.88
9	BOOTLID RUBBER	1.0	186.50	25	139.88
10	BOOTLID LOGO - VIOS	1.0	59.30	25	44.48
11	BOOTLID LOGO - E	1.0	49.50	25	37.13
12	BOOTLID EMBLEM	1.0	59.50	25	44.63
List Price - Parts Sub Total					1,479.10
13	REAR FENDER LH - REPAIR	1.0			
14	BOOTLID - REPAIR	1.0			
15	SPARE TYRE PANEL - REPAIR	1.0			
16	REVERSE SENSOR	1.0	280.00	0	280.00
17	REAR BUMPER LOWER SPOILER	1.0	680.00	0	680.00
Special Nett Price - Parts Sub Total					960.00
Parts Total					2,439.10
18	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	700.00	0	700.00
19	SPRAY PAINT ON THE AFFECTED AREAS	1.0	800.00	0	800.00
20	ANTI-RUST COATING	1.0	100.00	0	100.00
21	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					1,750.00
SINGAPORE DOLLARS : FOUR THOUSAND FOUR HUNDRED EIGHTY-TWO AND CENTS THIRTY-FOUR ONLY					
Less Excess					0.00
SUBTOTAL					4,189.10
GST 7.00%					293.24
TOTAL					4,482.34

Date of accident : 20/07/2020 02:15 PM Place : SIN MING DRIVE > SIN MING ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE