S/No	Qty	Items	Unit Price	A	mount
					100
1		replace, cut, weld, knock out or parts, inclusive of replacemen	dents to straighten accident parts as- nt parts.	\$	1,500.00
2	To putty and spray paint on all accident damage parts and other accident affected areas		\$	1,200.00	
3	Apply rust pr	oofing on the adjacent panels		\$	100.00 60
4	To supply un	der coating / putty on parts rep	laced	\$	80.00
5	To perform w	ater seepage test after repair		\$	80.00 ×
6	To reset engin	e management system with dis	agnostic fault	\$	150.00
7	Disconned and check electrical wiring, harness, wire socket			\$	80.00 30
8	Remove and re	eplace front windscreen		\$	150.00 10
12	Remove and refit rear end panel lining and garnish to fecilitate repair			\$	80.00 62
13	Remove and replace exhaust pipe/system to facilitate repair		\$	80.00 5	
	7-6	Dans			
	( )	y   ) .	TOTAL AMOUNT	:_\$	3,500.00
		nen a V	OVERALL COST	: \$	4,030.00
	After En	Days.  m repar.  repar photos  Qiaf.  [7/2020.	LICK Auto Consultants hence the Repairer of the following; To resurvey before/after spray pair To display damaged part(s) during of Parts prices are subject to confirme Third party survey is on a "Without of No illegal modification(s) is allowed Supplementary item(s) must be reside subject to finel approval from insu		
	27	17/2020.	Acknowledged by Repairer		