



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALAN'S UNITED AUTO PTE LTD

Ref : CS/TP20007577/Ksf3e2

BLK 7 SIN MING INDUSTRIAL ESTATE #01-76
SINGAPORE 575642

Date : 16-09-2020



ON BEHALF OF SOH TECK SOON

Code : TP023

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLA 4333R
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	22/07/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA 6 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6GJ1072G0224706	Colour	METALLIC RED
Odometer	162766	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	FALKEN	6 mm
L/H Front Tyre	225/55 R17	FALKEN	6 mm
R/H Rear Tyre	225/55 R17	FALKEN	6 mm
L/H Rear Tyre	225/55 R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE FOUND DAMAGED AT THE FRONT WINDSCREEN AND SAME BODY PAINT WORK AFFECTED AT THE TIME OF INSPECTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/07/2020	Inspection Date	22/07/2020
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**