

ASS. REC. BY:

REF: CS3/FCI20007602/f3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): JASON TEA of FCI Date/Time: 23/7/2020 1:12 PM

Estimated Cost: Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMP 1073U Insured: SHC 2109Y

at Workshop m/s Teamwork Garage Pte Ltd Tel: 68442475

of 53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park

Policy No: Claim No: D20002905MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 20-7-2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 23-7-20 1.24P.M Person Contacted: SHU SHAN Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SMP 1073U- NA/LIP20007502/z4 DOA : 20/07/2020
	SHC 2109Y- NA/LIP20007502/z4 DOA : 20/07/2020