

TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6385 1171

Vehicle No: SJE7301R
Model No. Honda Civic
Chassis no. *

Accident Date : 20/07/2020
Owner : Mohd Noor B AB Hamid
Date of Estimate : 03/09/2020

Estimate for Accident Vehicle No. SJE7301R

<u>List Items:</u>	Qty	Unit Price	Total Amount
1 Front door side mirror rh / <i>1R</i>	1		\$642.70
Sub-Total Amount =			\$642.70
Less parts-discount = 20%			\$128.54
Sub-Total =			\$514.16

Labour charges

1 Panel beating for replace and repair affected parts	\$200.00	<i>100</i>
2 Spray painting	\$200.00	<i>100</i>
	\$400.00	

Total parts	=	\$514.16
Total labour	=	\$400.00
Total Amount	=	\$914.16

Steve (LKK)

7/9/20, 11.00am

LKL ML

9 days

P/P

By BOL SA

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: