

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MS FIRST CAPITAL INSURANCE LIMITED
 38 ROBINSON ROAD #16-01
 CITYHOUSE SINGAPORE 068877

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP20/025

Date : 21/07/2020
 Vehicle Num. : SJP 9698L
 Make/Model : SUZUKI APV-7 SEATER 1.6-2009
 Chassis/Eng# : MHYGDB71V00302051/G16AID160897
 Accident Date : 20/07/2020
 Claim No. :
 Reference : LYB/SJP9698L/MSFIRST/tp/sy
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE	1,135.50	✓
2.	1	REAR TAILGATE RUBBER	118.00	X
3.	1	REAR TAILGATE ABSORBER/RH	50.10	X
4.	1	REAR EMBLEM 'APV'	56.00	✓
5.	1	REAR EMBLEM 'S'	42.15	✓
6.	1	REAR TAILGATE INNER TRIM BOARD	115.20	✓
7.	1	REAR TAILGATE LOCK UPPER	177.50	✓
8.	1	REAR BUMPER	557.55	✓
9.	1	REAR BUMPER REFLECTOR/RH	30.00	✓
10.	1	REAR BUMPER RETAINER/RH	29.10	✓
11.	1	REAR TAIL LAMP (RH)	157.75	✓
12.	1	REAR FENDER/RH	458.25	✓
13.	1	REAR FENDER INNER SHIELD	343.27	✓
14.	1	REAR PANEL	229.30	✓
15.	1	REAR ABSORBER	197.20	✓
16.	1	REAR LOWER ARM	216.90	✓
17.	1	REAR TAILGATE OUTER HANDLE CHROME	139.30	✓
18.	1	REAR PANEL TOP GARNISH	157.60	✓
19.	1	REAR SIDE STOPPER/RHS	26.20	✓
20.	1	REAR END PANEL AIRDUCT	38.00	✓
21.	1	REAR SILENCER	455.70	X
List Total S\$:			4,730.87	
15.00% Discount S\$:			709.63	
			4,021.24	

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD #16-01
 CITYHOUSE SINGAPORE 068877

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP20/025

Date : 21/07/2020
 Vehicle Num. : SJP 9698L
 Make/Model : SUZUKI APV-7 SEATER 1.6-2009
 Chassis/Engine : MHYGDB71V0G302051/G16A1610897
 Accident Date : 20/07/2020
 Claim No. :
 Reference : LYB/SJP9698L/MSFIRST/tp/isy
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
SPECIAL NETT ITEMS :				
1.	10	REAR TAILGATE INNER TRIM BOARD CLIPS	3.50	35.00 ✓
2.	1 SET	REAR FENDER INNER SHIELD CLIPS		12.00 ✓
3.	1	REAR W/SCREEN INNER SEAL		60.00 30.00 ✓
4.	1	REAR W/SCREEN SEALANT		60.00 30.00 ✓
5.	1	REAR NO PLATE (EMBOSS)		35.00 ✓
6.	1	REAR NO PLATE HOLDER		25.00 ✓
7.	1 SET	REAR REVERSE SENSOR		250.00 ✓
Special Nett Total S\$:				477.00
LABOUR :				
TOWING CHARGE			(8.11)	60.00 ✓
LABOUR CHARGE FOR REMOVAL & REFIX REAR W/SCREEN GLASS				150.00 120.00 ✓
LABOUR TO REMOVE/REFIX REAR SEAT, INTERIOR GARNISH, ETC				180.00 120.00 ✓
TO TRANSFER TAILGATE PARTS & FITTING TO NEW TAILGATE				120.00 60.00 ✓
TO CHECK WATER SEEPAGE				80.00 80.00 ✓
TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS				120.00 50.00 ✓
TO CHECK, REPAIR, REPLACED THE UNDER CARRIAGE PARTS				280.00 7 ✓

CONTINUE / ...

LKIC Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
 NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
 Tel No. : 64534177 Fax No. : 64593724
 E-Mail : limyewboo@singnet.com.sg
 Website : www.limyewboo.com.sg
 Buss. Reg. No. : 200514/00L

MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD #16-01
 CITYHOUSE SINGAPORE 068877

Attention : Motor Claim Department
 Contact : 65073848 Fax No. : 65073849

Estimate : TP20/025

Date : 21/07/2020
 Vehicle Num. : SJP 9698L
 Make/Model : SUZUKI APV-7 SEATER 1.6-2009
 Chassis/Eng# : MHYGDB71V00302051/G16AID160897
 Accident Date : 20/07/2020
 Claim No. :
 Reference : LYB/SJP9698LMSFIRST/p/sy
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO REPAIR, ALIGN & REPLACED REAR SILENCER TO CHECK COMPUTERISED WHEEL ALIGNMENT	150.00	7
		TO REMOVE & REFIX FUEL TANK IN ORDER TO FACILIATE REPAIR	120.00	60
		TO APPLY RUST-PROOFING ON REPAIRED/ REPLACED PANELS	120.00	90
		MOUNT VEHICLE ON JIG BENCH TO FACILIATE REPAIR JOB	350.00	7
		TO REPAIR, PANEL BEAT, RE-ALIGN ON RIGHT AFFECTED REAR DOOR, TO CUT & WELD ON REPLACED RIGHT REAR FENDER, END PANEL & LABOUR TO REPLACE ABOVE PARTS	1,200.00	1100
		TO PUTTY/PRIMER & SPRAY PAINT REAR TAILGATE, REAR END PANEL, RIGHT REAR FENDER, RIGHT REAR FENDER INNER PANEL REAR FLOOR PANEL, REAR BUMPER & SENSOR USING 2K PAINT	1,500.00	1000
		Labour Total S\$:		4,430.00




E. & O. E.

Total S\$: 8,928.24

=====

for LIM YEW BOO SPRAY PAINT CO.