

Shirley Hiew (LKK Auto)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Friday, 14 August 2020 1:45 pm
To: Shirley Hiew (LKK Auto)
Cc: SUR
Subject: RE: SJL6813A - Supplementary labour

Hi,

Labour to be adjusted before mandate approve.

Damage photos of fender support (wheelhouse) to be submitted – where is the damage photos? Labour is given for repair.

Thanks & Regards

Victor Koh
AIG

Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, August 14, 2020 10:08 AM
To: Koh, Victor-CK
Cc: SUR
Subject: [EXTERNAL] RE: SJL6813A - Supplementary labour

This message is from an external sender; be cautious with links and attachments.

Dear Victor,

Refer to your below email above matter. Our surveyor still negotiate the repair cost with Premium.

We are seeking your approval of the supplementary 2.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Thursday, 6 August 2020 3:42 pm
To: SUR <sur@lkkauto.com>
Subject: RE: SJL6813A - Supplementary labour

TO REMOVE AND REINSTALL RHS FRONT SEAT, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS- not necessary this labour for replacement of side sill.

From: Koh, Victor-CK
Sent: Thursday, August 06, 2020 3:36 PM
To: SUR
Subject: SJL6813A - Supplementary labour

Hi,

TO CUT OUT AND WELD RHS A-PILLAR AND RHS SILL PANEL – replacement of a pillar at 2 day \$1000.
TO RESPRAY RHS A-PILLAR AND RHS SILL PANEL AND DOOR ENTRANCES – Spray paint at 2 panel \$1100.
Damage photos of fender support (wheelhouse) to be submitted.
B/f paint needed.
Kindly adjust labour in report.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.