

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0511/2020/GW
Date 24-Jul-20
Service Advisor Glory Tan
Pages 1 OF 1
Regn No SJL 6813 A
Model No Audi A5 SB 2.0 TFS

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Front door chrome trim LHS <i>rec</i> ✓	\$ 157.00	
2	Engine mounting RHS <i>X</i>	\$ 417.00	
12/08/2020 <i>X</i> ③	Subframe console RHS <i>bt</i> ✓	\$ 467.00	
4	Front subframe <i>bt</i> ✓	\$ 1,869.00	
5	Front wishbone link RHS <i>bt</i> ✓	\$ 533.00	
6	Front suspension guide RHS <i>bt</i> ✓	\$ 932.00	
7	Front guide upper front RHS <i>bt</i> ✓	\$ 506.00	
8	Front guide upper rear RHS <i>bt</i> ✓	\$ 506.00	
9	Wheel bearing housing RHS <i>bt</i> ✓	\$ 957.00	
10	Swivel joint <i>bt</i> ✓	\$ 191.00	
11	Suspension forks RHS <i>bt</i> ✓	\$ 261.00	
12	Coupling rod RHS <i>bt</i> ✓	\$ 127.00	
13	Front shock absorber RHS <i>?</i>	\$ 289.00	
14	Steering rack <i>AWC report</i> ✓	\$ 6,234.00	
15	Tie rod end RHS <i>bt</i> ✓	\$ 195.00	
16	Roof lining <i>de</i> ✓	\$ 2,025.00	
17	Battery central protection <i>short</i> ✓	\$ 527.00	
18	Steering column <i>bt</i> ✓	\$ 2,214.00	
19	Water reservoir tank <i>de</i> ✓	\$ 141.00	
20	Anti-roll bar <i>bt</i> ✓	\$ 428.00	

TOTAL

\$ 18,976.00

For Premium Automobiles Pte Ltd

Authorised Signature

Paul
28/07/2020
Subject to
insurance
approval

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0511/2020/GW
Date 24-Jul-20
Service Advisor Glory Tan
Pages 1 OF 1
Regn No SJL 6813 A
Model No Audi A5 SB 2.0 TFS

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
21	A-pillar with sill panel RHS <i>bt</i>	\$ 2,154.00	
22	Chassis tag <i>new</i>	\$ 457.00	
23	Sill trim strip RHS <i>new</i>	\$ 119.00	
24	Potential distributor <i>bro</i>	\$ 527.00	

Labours

1	To remove and reinstall rhs front seat, floor carpets, electronic components and fuse trays.	s/n \$ 1,400.00	
2	To cut out and weld rhs A-pillar and rhs sill panel.	\$ 3,200.00	<i>1500</i> 2000
3	To respray rhs A-pillar and rhs sill panel and door entrance.	\$ 2,300.00	<i>1100</i> 1650
4	To repair wiring set for engine components.	s/n \$ 980.00	

TOTAL \$ 29,813.00 30,113.00

For Premium Automobiles Pte Ltd

Authorised Signature