



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20004949/Gyf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 04-08-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8251D	Veh. Inspected	SBC 37E
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20030528	Excess (\$)	0.00
Assign From	CARINE KEK	Assign Date	22/07/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ C 180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2043312G327705	Colour	WHITE
Odometer	89323	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45Z R17	MICHELIN	5 mm
L/H Front Tyre	225/45Z R17	MICHELIN	5 mm
R/H Rear Tyre	225/45Z R17	MICHELIN	5 mm
L/H Rear Tyre	225/45Z R17	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/03/2020	Inspection Date	06/04/2020
Survey held at	WAH YU AUTOMOTIVE BODY WORK 176 SIN MING DRIVE #05-09 SINGAPORE 575721		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------